

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
STOPSON	Deu I Mata, 104-110, 08029 Barcelona	INSULATION MATERIAL	Inspection and acceptance	INITEC ENERGÍA	C.T.CC. AES CARTAGENA	2004	
AIRSEC S.A..	PROGRES 6-8 E-08160 MONTMELÓ	COMPRESSOR	Inspection and acceptance	CompAir	IBERDROLA GENERACION CCC CASTELON iV	2006	
SPIRAX SARCO	E-08980 Sant Feliu de Llobregat	Steam Traps, SECURITY VALVES	Inspection and acceptance	REPSOL PETROLEO/INTECSA -UHDE	PLANTA DE BENCENO DE 190 Ktn/Año	2006	
SPIRAX SARCO	E-08980 Sant Feliu de Llobregat	Steam Traps, SECURITY VALVES	Inspection and acceptance	CEPSA	SERVICIOS AUXILIARES	2006	
SPIRAX SARCO	E-08980 Sant Feliu de Llobregat	Steam Traps, SECURITY VALVES	Inspection and acceptance	ARYA SASOL POLYMER COMPANY	OFFSITE FACILITIES-BANDAR ASSALUYEH-IRAN	2006	
AIRSEC	MONTMELO	Air dryer	Inspection and acceptance			2006	
CONSTRUCCIONES NUREIG	REUS	Anchor placement jigs	Inspection and acceptance			2006	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	GULF PETROCHEMICAL SERVICES &TRADING	TPO-2008-142D MAMUL & THULEILAT/C-162	2006	
ROS ROCA INDOX	TARREGA	GAS TANKER	Inspection and acceptance			2006	
SUINCA SA	CABRERA DE MAR	LEVEL DETECTORS	Inspection and acceptance			2006	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance			2006	
DECOLLATGE SERVI	HOSPITALET DE LLOBREGAT	VALVES	Inspection and acceptance			2006	
BACHILLER	MOLLET	VESSEL	Inspection and acceptance			2006	
AGUILAR & SALAS	Irlanda 5, Les Franqueses del Vallès - Barcelona E 08520	Heat Exchanger/presure vessels	Inspection and acceptance	UOP	KPPC/Bechtel-Aromatic Project	2007	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance	J&P ENERGY & INDUSTRIAL PROJECTS S.A.	WAHA/FAREGH FIELD	2008	
RINGO VALVES	E-50720 ZARAGOZA	BALL VALVES	Inspection and acceptance	BLACK CAT CONSTRUCTION W.L.L.	GTC/07/158/FP	2008	
ECONTROL VALVES	Pol. Industrial Constantí calle Grecia, edificio B4 43120 Constantí, Tarragona	VALVES	Inspection and acceptance	PETRO GAS PARSA	UNKOWN	2008	
Asea Brown Boveri S.A	SANT QUIRZE	ELECTRICAL MOTORS	Inspection and acceptance	Foster Wheeler	REPSOL YPF - PETRONOR/ REPSOL ADI-1000 IUI-13226 FW 1DD-5522A	2008	
EMERSON PROCESS MANAGEMENT, S.L.	Pl. La Bastida, naves 2&3 Rubi, Spain 08191	VALVES	Inspection and acceptance	Foster Wheeler	UNIDADES DE CRUDO,VACÍO Y CONCENTRACION DE GASES, LA RABIDA	2008	
EMERSON PROCESS MANAGEMENT, S.L.	Pl. La Bastida, naves 2&3 Rubi, Spain 08191	VALVES	Inspection and acceptance	BP refinera CASTELLON	VALVULAS DE CONTROL TODO NADA II	2008	
TRAMECA	REUS	JIGS	Inspection and acceptance	UOP LLC	RPBC CCR project	2008	
COPCISA	TARRAGONA	JIGS	Inspection and acceptance	UOP LLC	RPBC CCR project	2008	
SCHWARTZ-HARTMONT	VILASECA	JIGS	Inspection and acceptance	UOP LLC	RPBC CCR project	2008	
ECONTROL VALVES	Pol. Industrial Constantí calle Grecia, edificio B4 43120 Constantí, Tarragona	VALVES	Inspection and acceptance	DODSAL PTE Ltd	M-2005-005	2008	
ECONTROL VALVES	Pol. Industrial Constantí calle Grecia, edificio B4 43120 Constantí, Tarragona	VALVES	Inspection and acceptance	PETRO GAS PARSA	ISI-001168 / IRN 1279227	2008	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
RINGO VALVES	E-50720 ZARAGOZA	BALL VALVES	Inspection and acceptance	QATAR PETROLIUM	DOHA MOTORS	2008	
SPIRAX SARCO	E-08980 Sant Feliu de Llobregat	Steam Traps, SECURITY VALVES	Inspection and acceptance	CEPSA	MORPHYLANE	2008	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance	Maersk Oil Qatar	6048-2007-70087-BC	2008	
EMERSON PROCESS MANAGEMENT, S.L.	Pl. La Bastida, naves 2&3 Rubi, Spain 08191	Control Valves & Regulators	Inspection and acceptance	IBERDROLA	Kuraymat	2009	
AIRJET, S.A.	Pau Claris, 138 08009 – BARCELONA (ESPAÑA)	Filters, 3KM0-T02 / 3KM0-T03	Inspection and acceptance	WORLEY PARSONS	MA'ADEN PHOSPHATE PROJECT	2009	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	J&P ENERGY & INDUSTRIAL PROJECTS S.A.	WAHA/FAREGH FIELD DEVELOPMENT PHASE 2	2009	
BAC AUSTRALIA	Unit 2 / 54 Hurlstone Dr New Plymouth, NZ	BULK ACTUATED MANUAL VALVES	Inspection and acceptance	ORIGIN ENERGY RESOURCES (KUPE) LIMITED	KUPE GAS PROJECT – CONDENSATE TANK FARM	2009	
E. BACHILLER S.A.	Can Guasch, 3 / Pol. Ind. Levante E- 08150 Partes des Valles	AMMONIA EVAPORATORS	Inspection and acceptance	Ma'aden	DAP GRANULAION PLANT - 10411	2009	
Grupo General Cable Services (Europe) Limited	XLPE INSULATED STEEL WIRE ARMOURED 600/1000V CABLE	INSULATED, STEEL	Inspection and acceptance	Parsons Energy & Chemicals	Sakhalin II OPF	2009	
COOPER CROUSE-HINDS	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	Gas Turbine . Emergency lube oil pump motor EEx-d panel/JB	Inspection and acceptance	CEAG	SO 17730 FPSO P57 Project	2009	
ABB FABRICA DE TRANSFORMADORE S	Carretera de Madrid, km 314 ZARAGOZA	Bell Conveyor System	Inspection and acceptance	Aker Solutions	Minera Esperanza	2009	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	J&P ENERGY & INDUSTRIAL PROJECTS S.A.	WAHA/FAREGH FIELD DEVELOPMENT PHASE 2	2009	
COOPER CROUSE-HINDS	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	Refer to the papa. 1.0 Material descriptions In the detail inspection activities report.	Inspection and acceptance	Salalah Methanol Company LLC	Salalah Methanol Project	2009	
PROCONTROL SL	C/Dinamarca-Parcel.les 3 i 4, Nau 9 43121 Constantí (Tarragona)	ARMARIO GENERAL DE DISTRIBUCIÓN	Inspection and acceptance	ENDESA CTCC BESOS 5 (840MW)		2009	
PROCONTROL SL	C/Dinamarca-Parcel.les 3 i 4, Nau 9 43121 Constantí (Tarragona)		Inspection and acceptance	C.T.C.C PORT DE BARCELONA GAS NATURAL		2009	
PROCONTROL SL	C/Dinamarca-Parcel.les 3 i 4, Nau 9 43121 Constantí (Tarragona)	ARMARIO GENERAL DE DISTRIBUCIÓN	Inspection and acceptance	CTCC BESOS-5		2009	
PROCONTROL SL	C/Dinamarca-Parcel.les 3 i 4, Nau 9 43121 Constantí (Tarragona)		Inspection and acceptance	TECNICAS REUNIDAS	C.C.C. PORT DE BARCELONA Gas Natural, S.D.G, S.A.	2009	
CYMI SA	SANT BOI DE LLOBREGAT BARCELONA	Centro Control de Motores	Inspection and acceptance	CCC PORT DE BARCELONA GAS NATURAL SDG SA		2009	
COAPSA	St.Miquel de Toudell, 7 P.I.Can Mir VILADECALLS	7380-0211 planta trat de efluentes CCM	Inspection and acceptance	CTCC MONTOIR		2009	
CYMI SA	SANT BOI DE LLOBREGAT BARCELONA		Inspection and acceptance	TECNICAS REUNIDAS/ENDESA		2009	
ELECTRA MOLINS	SANT VICENÇ DELS HORTS	EMERGENCY DIESEL GENERATOR	Inspection and acceptance	MA'ADEN	DAP GRANUTATION PLANT	2009	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
COOPER CROUSE	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	Interconex ACPM/Cajas de Fuerza	Inspection and acceptance	CEPSA REFINERÍA LA RÁBIDA (HUELVA)	CEPSA-711.95 / INTECSA-14162	2009	
EMERSON PROCESS MANAGEMENT, S.L.	Pl. La Bastida, naves 2&3 Rubi, Spain 08191	Control Valves & Regulators	Inspection and acceptance	IBERDROLA	Kuraymat	2009	
Comercial de Valvulas y Accesorios, S.L.	Pol. Ind. Polizur, CL Bosc Tancat, 6 Naves 2 y 3 08290 CERDANYOLA DEL VALLES (Barcelona)	Valves PTA	Inspection and acceptance	UTE Hassi R'mel Construction	Hassi R'Mel Construction	2009	
REYCO, S.L.	Pol. Ind. Can Fuster, Nave 14 Ctra. N-II, Km. 592,85 SANT ANDREU DE LA BARCA, BARCELONA		Inspection and acceptance	ABENER ENERGIA, S.A.	ISCC AIN BENI MATAR	2009	
BACHILLER	MOLLET		Inspection and acceptance	DRAGADOS GROUP JV (DJV3)	LNG PLANT	2009	
Asea Brown Boveri S.A	Asea Brown Boveri, S.A. Street, San Romualdo,13 Madrid, Madrid 28037 Spain	MOTORES ELECTRICOS Y VARIADORES DE VELOCIDAD	Inspection and acceptance	REPSOL YPF		2009	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVE	Inspection and acceptance		THUNDER HAWK	2009	
SPIRAX SARCO, S.A	E-08980 Sant Feliu de Llobregat	STRAINERS	Inspection and acceptance	Medgaz S. A.	ONSHORE FACILITIES EPIC CONTRACT	2009	
IDAGUA SA	CARRER CUZCO, 47 BARCELONA	POMPES EAU DESALINISEE	Inspection and acceptance	EMBALEX	TERGA	2009	
OLLEARIS S.A.	Calle Moli s/n , Polígono Industrial Martorelles, MARTORELLES, Spain	GRP PIPES NB2200	Inspection and acceptance	RWE Npower	Pembroke CCGT	2009	
AMG	Via Trajana, 50-56. Nave 40 - 08020 - BARCELONA / Spain	WATER TREATMENT PLANT (D05)	Inspection and acceptance	IDAGUA	SHOAIBA	2009	
RINGO VALVES	E-50720 ZARAGOZA	BALL VALVE	Inspection and acceptance	DOHA MOTORS & TRADING CO.	GTC/07/158/FP	2009	
ECONTROL VALVES	Pol. Industrial Constantí calle Grecia, edificio B4 43120 Constantí, Tarragona	MOTOR OPERATED VALVES	Inspection and acceptance	Al Khafji Operations	PROJECT 3047-R0	2009	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	J&P ENERGY & INDUSTRIAL PROJECTS S.A.	WAHA/FAREGH FIELD DEVELOPMENT PHASE 2	2009	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	J&P ENERGY & INDUSTRIAL PROJECTS S.A.	WAHA/FAREGH FIELD DEVELOPMENT PHASE 2	2009	
FABRISEM SL	Ctra. Zaragoza - Sariena (A-129), Km 23	TERMINAL CHASSIS, HABOUR CONTAINER TRAILER SPC652E	Inspection and acceptance	Qatar Petroleum	Berth 7 Mesaieed Port	2009	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	J&P ENERGY & INDUSTRIAL PROJECTS S.A.	JP-175/OIL FLOW TIE-IN MATERIALS FOR 5I-17 AND 5I-18	2009	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	KOC	Al-Kattar	2010	
COOPER CROUSE	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	LIGHTING FIXTURES – HAZARDOUS TYPE	Inspection and acceptance	PETROFAC DUBAI	KOC PIPELINE JI-192	2010	
COOPER CROUSE	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	LIGHTING FIXTURES	Inspection and acceptance	PETROFAC	EL MERK	2010	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	CAMERON CVM PROJECT GROUP	Chayvo OPF Expansion	2010	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALLVALVES	Inspection and acceptance	FLUOR	Chayvo OPF Expansion	2010	
COOPER CROUSE	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	FLOOD LIGHTING FIXTURE LOT	Inspection and acceptance	Abu Dhabi Oil Refining Company	Green Diesel Project	2010	
PT. OMIC Consulting Services Indonesia	Jl. DR Saharjo 111, Jakata 12810	METAL DETECTION MACHINE	Inspection and acceptance	Surveyor Indonesia (Jakarta Branch)		2010	
SAIDI	Telemática, 11 08110 Montcada I Reixac (Barcelona)	METAL VALVES	Inspection and acceptance	IBERDROLA	CC Koudiet	2010	
ABB FABRICA DE TRANSFORMADORES	Carretera de Madrid, km 314 ZARAGOZA	FLOW PRIMARY ELEMENTS	Inspection and acceptance	IBERDROLA	CC Koudiet	2010	
GE POWER CONTROLS	Ave.Josep Taradellas, 2, 08225 Terrassa, (Barcelona)	POWER CENTERS	Inspection and acceptance	IBERDROLA	CC Koudiet	2010	
NOVAIR-MTA	Ronda Shimizu 6 Vacarisses (Barcelona)	ADSORPTION DRYER	Inspection and acceptance	IBERDROLA	CC Koudiet	2010	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	UTE Andasol III	Proyecto Helioenergy 1,Proyecto Helioenergy 2	2010	
KITZ	Calle Ramon Viñas, 8 Sant Adria de Besos, Barcelona 08930 Spain	BALL VALVES	Inspection and acceptance	IBERDROLA		2010	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	MANUAL BALL VALVES FOR SOLAR FIELD	Inspection and acceptance	IBERDROLA	UTE Andasol III	2010	
KITZ	Calle Ramon Viñas, 8 Sant Adria de Besos, Barcelona 08930 Spain	BALL VALVES	Inspection and acceptance	IBERDROLA	CC SUGRES	2010	
DEISA	Pol. Ind. Can Parellada. Jupiter, 53 Terrassa, Barcelona 08228 Spain	PLASTIC CENTRIFUGAL PUMPS	Inspection and acceptance	IBERDROLA	CC Koudiet	2010	
ISAMA TECNICS GRUP SL	Llobateres, 20 08210 Barbera Valles (Barcelona)	POMPES DOSEUSES ET POMPES TRANSVASEMENT	Inspection and acceptance	IBERDROLA	CC Koudiet	2010	
IAC Stopson Espanhola S/A	Deu y Mata 104-110 Barcelona, 08029	PANEL IAC VETICAL CLADDING (ACOUSTING PANELS)	Inspection and acceptance	Construtora Norberto Odebrecht, Petroquimica Suape	PTA Plant - Petroquimica Suape	2010	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)		Inspection and acceptance	EXXON NEFTEGAS LTD.	Sakhalin	2010	
PT. OMIC Consulting Services Indonesia	Jl. DR Saharjo 111, Jakata 12810	METAL DETECTION MACHINE	Inspection and acceptance	Surveyor Indonesia (Jakarta Branch)		2010	
COYARD	1 RUE DE LA NOUETTE 49070 BEAUCOUZE – FRANCE	GATE VALVE	Inspection and acceptance	OIEC	SIRRI ISLAND	2010	
Plastoquímica	Pol. Industrial Font Santa Mossen Cinto Verdaguer s/n Sant Joan d'Espí -Barcelona	PEHD DOSING TANKS	Inspection and acceptance	LPC		2010	
ECONTROL VALVES	Pol. Industrial Constantí calle Grecia, edificio B4 43120 Constantí, Tarragona	VALVES	Inspection and acceptance	Kuwait Oil Company		2010	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	Al-Khadda		2010	
JCF Fluid Flow FZE	Sharjah, UEA	FINAL INSPECTION CONTRACT	Inspection and acceptance	Kuwait Oil Company		2010	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
COOPER CROUSE	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	POWER BULK MATERIAL	Inspection and acceptance	Saipem India	BS-160	2010	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	Al-Khadda	Replacement of ESDV's/AOV's/Shutdow Control Valves at BS-140 & Bs-150	2010	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Reference Documents for Inspection of OPGW & U/G NMFOC and accessories	Inspection and acceptance	MEEDCO	NEW MAKKAH NORTH 380KV OVERHEAD TRANSMISSION LINES	2011	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Reference Documents for Inspection of OPGW & U/G NMFOC and Joint Boxes	Inspection and acceptance	SAUDI SERVICES FOR ELECTROMECHANIC WORKS CO. LTD	380KV OHTL FROM JUBAIL 380KV/132KV S/S TO JUBAIL COMMUNITY-2 CKT-1&2 AND JUBAIL COMMUNITY-2 TO MA'ADEN CKT-1&2	2011	
GENERAL CABLE	Rusiñol 63, Manlleu, Barcelona 08560	TECHNICAL SPECIFICATIONS	Inspection and acceptance	PDVSA	Delta Caribe Oriental Project	2011	
Measurement PLUS Pty Ltd	Level 5, 350 Collins Street, Melbourne Victoria 3000	Floating & Trunnion Bare Stem Ball valves (26 pieces 1" to 10")	Inspection and acceptance	WORLEY PARSONS	YOLLA MLE PROJECT	2011	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	WORLEY PARSONS		2011	
Measurement PLUS Pty Ltd	Level 5, 350 Collins Street, Melbourne Victoria 3000	Floating & Trunnion Bare Stem Ball valves (26 pieces 1" to 10")	Inspection and acceptance	WORLEY PARSONS	YOLLA MLE PROJECT	2011	
ECOTEC	Pol. Ind. Bufalvent, C/Esteve Terradas, 37A Manresa, Barcelona 08243	DECANTADORES	Inspection and acceptance	ABENER	SOLACOR 1	2011	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	LABORATORIOS DE CONTROL DE LA CALIDAD	Inspection and acceptance	CONTROL Y MOTAJES INDUSTRIALES		2011	
MECESA	Joan Monpeo 35 Terrassa, Barcelona 08223	CONDENSATE POTS AND MANIFOLDS	Inspection and acceptance	IBERDROLA	Lithuania	2011	
IAC Stopson Espanhola S/A	Deu y Mata 104-110 Barcelona, 08029	SILENCERS	Inspection and acceptance	Embrateco Consultoria		2011	
IAC Stopson Espanhola S/A	Deu y Mata 104-110 Barcelona, 08029	SILENCIERS	Inspection and acceptance	JARAGUA EQUIPAMENTOS INDUSTRIAIS		2011	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	EXXON NEFTEGAS LTD.	Sakhalin-1 – 156445-5010	2011	
DEPISA	Nacional 240, km.9,25-43.152- Perafort-Tarragona/Spain	PIPES AND FITTING	Inspection and acceptance		LPC	2011	
MECESA MECANICAEGARENSE	Joan Monpeo 31-37, ES-08223 Terrassa-Barcelona/Spain	TUBING AND FITTING MATERIAL	Inspection and acceptance		LPC	2011	
Plastoquímica	Pol. Industrial Font Santa Mossen Cinto Verdaguer s/n Sant Joan d'Espí -Barcelona	DEGASSER AIR BLOWER	Inspection and acceptance		LPC	2011	
Koplogistic	Koplogistic Street F18 Sector. C Zona Franca Barcelona.	ELCOMETER	Inspection and acceptance		LORESTAN PC	2011	
Alsmea	Pol. Ind. Parets Valles, C-17, Km. 14,5 08150 Barcelona	SEAMLESS PIPE	Inspection and acceptance		LPC	2011	
JCF Fluid Flow FZE	Sharjah, UEA	BALL VALVES	Inspection and acceptance	Kuwait Oil Company	REPLACEMENT OF ESDVs/AOVs/SHUTDOWN CONTROL VALVES AT BS-140 & BS-150	2011	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance	WORLEY PARSONS	YOLLA MLE PROJECT	2011	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
STOPSON IAC ESPAÑOLA SA	Deu I Mata, 104-110 08029 Barcelona	SILENCERS	Inspection and acceptance	JARAGUA EQUIPAMENTOS INDUSTRIAIS	REFINERIA DO NORDESTE	2011	
TRONZADORAS MG	Pol Ind. Font de la Parera, s/n 08430 La Roca del Valles, Barcelona	Hydraulic shearin machine	Inspection and acceptance	KINGDOM OF ARABIA		2011	
MAIVISA	Serra Vallmorena 8-10 P.I. Vallmorena II Vilassar de Dalt, Barcelona	Heat Exchanger/presure vessels	Inspection and acceptance	UTE Abener Teyma Helios Campo de San Juan I	Helios	2011	
LLOVERAS	CTRA DE RUBI, 284 TERRASSA 08228	Chocolate Machine	Inspection and acceptance	SAUDI ARABIA		2011	
MECESA	Joan Monpeo 35 Terrassa, Barcelona 08223	Condensate pots and manifolds	Inspection and acceptance	IBERDROLA	Lithuania	2011	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVE	Inspection and acceptance	JGC International Company/ TATWEER	TATWEER NEW WELL MANIFOLD FACILITIES	2012	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	TATWEER PETROLEUM BAHRAIN FIELD DEVELOPMENT COMPANY W.L.L	THREE - PHASE SEPARATOR SKID PACKAGES - 4 NOS	2012	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	TATWEER PETROLEUM BAHRAIN FIELD DEVELOPMENT COMPANY W.L.L	THREE - PHASE SEPARATOR SKID PACKAGES - 4 NOS	2012	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	MANUAL BALL VALVES	Inspection and acceptance	TATWEER PETROLEUM BAHRAIN FIELD DEVELOPMENT COMPANY W.L.L		2012	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	Ramsis Engineering	THREE - PHASE SEPARATOR SKID PACKAGES - 4 NOS	2012	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	Ramsis Engineering	TATWEER EPC Pipe Line/TATWEER –CONSTRUCT	2012	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance		BIG FOOT PROJECT	2012	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance	Chevron	C645-BIG FOOT	2012	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance	EXXON NEFTEGAS LTD.	Sakhalin-1 – 156445-5010	2012	
Koplogistic	Koplogistic Street F18 Sector. C Zona Francea Barcelona Port	Pumps and Resin for bed exchangers	Inspection and acceptance		LPC	2012	
Vector and Wellheads Engineering SL	Utebo, Zaragoza, Spain	Forged Steel Gate, Globe and Check Small Bore Valves	Inspection and acceptance	TOLEDO ELECTRICAL & MECHANICAL WORK	BAB MODIFICATION – ABBR Project	2012	
Schwartz-Hautmont Construcciones Metalicas SA	9 Aveida De La Canonja Vila-Seca, Tarragona	Brazed Aluminum Core Heat Exchangers and cold box	Inspection and acceptance	GLNG Operations Pty Ltd	GLNG Plant and Port Project	2012	
Vector and Wellheads Engineering SL	Utebo, Zaragoza, Spain	BALL VALVE	Inspection and acceptance	TOLEDO ELECTRICAL & MECHANICAL WORK	ABBR Project	2012	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	On/Off valves	Inspection and acceptance	TAKREER (Abu Dhabi Oil Refining Company)	Ruwais Refinery Expansion Project	2012	
AGUILAR & SALAS	IRLANDA 5, LES FRANQUESES DEL VALLÈS - BARCELONA E 08520	Brazed Aluminum Core Heat Exchangers and cold box	Inspection and acceptance	GLNG Operations Pty Ltd	GLNG Plant and Port Project	2012	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
RINGO VALVES	E-50720 ZARAGOZA	VALVES	Inspection and acceptance	GASCO Procurement	Various	2012	
Vector and Wellheads Engineering SL	Utebo, Zaragoza, Spain	BALL VALVES	Inspection and acceptance	TOLEDO ELECTRICAL & MECHANICAL WORK	ABBR Project	2012	
COOPER CROUSE	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	Ex PANEL	Inspection and acceptance	TAKREER (Abu Dhabi Oil Refining Company)	Ruwais Refinery Expansion Project(Pkg 2)	2012	
LINDE	Carrer Irlanda 5 08520 Les Franqueses Del Valles Spain	Brazed Aluminum Core Heat Exchangers and cold box	Inspection and acceptance	GLNG Operations Pty Ltd	GLNG Plant and Port Project	2012	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance	Chevron	C645-BIG FOOT	2012	
VECTOR	Utebo, Zaragoza, Spain	BALL VALVES	Inspection and acceptance	TOLEDO ELECTRICAL & MECHANICAL WORK	BAB MODIFICATION – ABBR Project	2012	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	TATWEER PETROLEUM BAHRAIN FIELD	THREE - PHASE SEPARATOR SKID PACKAGES - 4 NOS	2012	
RINGO VALVES	E-50720 ZARAGOZA	BALL VALVES	Inspection and acceptance	GASCO Procurement	Various	2012	
EMERSON PROCESS MANAGEMENT, S.L.	Pl. La Bastida, naves 2&3 Rubi, Spain 08192	CABLES	Inspection and acceptance		THIRD PARTY INSPECTION SERVICES	2012	
TOP CABLE CO.	Parc de Activitats Economiques Rubi, Barcelona 01891 Spain	VALVES	Inspection and acceptance	YACIMIENTOS PETROLÍFEROS FISCALES BOLIVIANOS (YPFB)	GRAN CHACO L.S. PLANT (BOLIVIA)	2013	
VCF S.A.	Capiscol 6 1ro. 4, Madrid	Control Valves	Inspection and acceptance	Initec Plantas Industriales, S. A.		2013	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	Qatar Petroleum	Various 4300072673	2013	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	MANUAL & ACTUATED BALL VALVES	Inspection and acceptance	KOC	Replacement of HIC Affected Equipment in SK GCs 3, 4, 7, 8, & 21	2013	
AGUILAR & SALAS	Irlanda 5, Les Franqueses del Vallès - Barcelona E 08520	Heat Exchanger/presure vessels	Inspection and acceptance	GLNG Operations Pty Ltd	GLNG Plant and Port Project	2013	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	ESDV, SBDV & MOV BALL VALVES	Inspection and acceptance	KOC/Gulf Spic General Trad. & Cont. Co.	Replacement of HIC Affected Equipment in SK GCs 3, 4, 7, 8, & 21	2013	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	Petroleum Development Oman (PDO)	NRPS AP FLARE GAS RECOVERY PROJECT C.OM.NIM.HS.12.001	2013	
CASALS CARDONA	Ferran Casablanacas, 24 08240 Manresa	PVDF PUMPS	Inspection and acceptance	TSU PROJECTS	IMOURAREN URANIUM PROJECT	2014	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SDV & MOV VALVES	Inspection and acceptance	KJO	New Hout Crude Transmission Line	2014	
ESTRUAGUA	Pol Industrial El Ramassar Carretera de Granollers a Cardedeu KM1,5		Inspection and acceptance	UTE ABENER INABENSA CENTRO MOLEROS	CENTRO MOLEROS 264	2014	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	Enhancement of EPF-50 Plant Integrity to KOC standards	2014	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MINUTES OF VENDOR PRE-INSPECTION MEETING (VPIM)	2014	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MANUAL GATE & CHECK VALVES EMERGENCY SHUTDOWN VALVES AND MOTOR OPERATED VALVE VALVES	2014	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MANUAL GATE & CHECK VALVES EMERGENCY SHUTDOWN VALVES AND MOTOR OPERATED VALVE VALVES	2014	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MANUAL GATE & CHECK VALVES EMERGENCY SHUTDOWN VALVES AND MOTOR OPERATED VALVE VALVES	2014	
SEDEM SA	Alts Forns, 52 – 08038 Barcelona	Magnetic Multi-float switch Magnetic Level Gauge	Inspection and acceptance	COBRA	CENTRAL TERMICA RECKA	2015	
HIDRACAR SA	Pol Industrial Les Vives Carrer Anaïs Nin, 14 08295 Sant Vicenç de Castellet Barcelona Spain	PULS.DAMPER(PD-1001-A/S-01-20)ANSI FLANGE	Inspection and acceptance	PERSIA Oil & Gas industry Development Company	Yaran North Oil Field Developement	2015	
SAMSON SA	Avd. Can Sucarrats ,104. 08191 Rubi (Barcelona)	SELF OPERATED VALVES	Inspection and acceptance	INTECSA	IBN SINA POLYOXYMETHYLENE PROJECT	2015	
SAIDI	Avda del Llano Castellano 15 5ª planta MADRID	3 VALVES BART SHAFT	Inspection and acceptance	INTECSA	16130 MAÁDEN IU&O	2015	
SAIDI	Avda del Llano Castellano 15 5ª planta MADRID	ON OFF VALVES	Inspection and acceptance	INTECSA	16130 MAÁDEN IU&O	2015	
METALTEST	08160 Montmeló	613-PU-1101-SeaWater Filtration Package	Inspection and acceptance	Satah Al-Razboot	Satah Al-Razboot (SARB) SWTP Project	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MANUAL GATE & CHECK VALVES EMERGENCY SHUTDOWN VALVES AND MOTOR OPERATED VALVE VALVES	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MANUAL GATE & CHECK VALVES EMERGENCY SHUTDOWN VALVES AND MOTOR OPERATED VALVE VALVES	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MANUAL GATE & CHECK VALVES EMERGENCY SHUTDOWN VALVES AND MOTOR OPERATED VALVE VALVES	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	SHUTDOWN VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MANUAL GATE & CHECK VALVES EMERGENCY SHUTDOWN VALVES AND MOTOR OPERATED VALVE VALVES	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	Ball Valves	Inspection and acceptance	Qatar Petroleum	STOCK MATERIALS	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	Ball Valves	Inspection and acceptance	Qatar Petroleum	STOCK MATERIALS	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	Ball Valves	Inspection and acceptance	Qatar Petroleum	STOCK MATERIALS	2015	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	valves of the 3rd batch s/n 86286 20 86287 20	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	MANUAL GATE & CHECK VALVES EMERGENCY SHUTDOWN VALVES AND MOTOR OPERATED VALVE VALVES	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	Manual Ball Valves, ESDVs, SBDVs & MOVs	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	Project – 14051098 – Replacement of HIC affected Non-NACE Separators and gas Scrubbers at SEK GCs 1, 6, 8 & 11	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	Trunnion Ball Valves 12" 300# Floating Ball Valves 2" 300#	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	1 x Trunnion Ball Valves 12" 300#, 3 x Floating Ball Valves 2" 300#	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	MANUAL, ESDV, SBDV & MOV BALL VALVES	Inspection and acceptance	KOC	Replacement of HIC affected Non-NACE Separators and gas Scrubbers at SEK GCs 1, 6, 8 & 11	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	ESDV-SBDV-BDV VALVES	Inspection and acceptance	KOC	EPF-50 INTEGRITY REVAMP WORKS	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	1 x Trunnion Ball Valves 12" 300#, 3 x Floating Ball Valves 2" 300#	Inspection and acceptance	KOC		2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	KOC		2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	ON OFF VALVES	Inspection and acceptance	IBN SINA	16100 POM IBN SINA	2015	
ITRON SPAIN SLU	Montornés del Vallés, Catalunya, E-08170, Spain	Meter Prover with Laptop Computer UTG400	Inspection and acceptance	SSGC	Third Party Inspection	2015	
INIMO	Carrer de Luxemburg, 2, 08769 Castellví de Rosanes, Barcelona	ODORISERS	Inspection and acceptance	YACIMIENTOS PETROLÍFEROS FISCALES BOLIVIANOS (YPFB)	Planta de GNL, EST y Cisternas	2015	
DIMASA	Ronda Shimizu, 10 08233 Vacarisses	Atmospheric GRPF Tanks - Permeate tank 100m3	Inspection and acceptance	IBERDROLA	Lichterfelde 150 MW Plant (Germany)	2015	
BAC VALVES S.A.	POLÍGONO INDUSTRIAL SUROESTE 08192 SANT QUIRZE DEL VALLÉS (BARCELONA)	53P-206 A/B Motor	Inspection and acceptance	FRIATEC AG Div. Rheinhütte	LA PAMPILLA	2015	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	OMAN GAS COMPANY S.A.O.C.	VARIOUS	2015	
ARCAMO	Polígon Industrial Riu Clar, c/Del Coure , Parcela 167 43006 TARRAGONA	DRAWING: CAP FOR TUBING END STRAIGHT FITTING CONNECTOR (MALE) STRAIGHT FITTING CONNECTOR (MALE) STRAIGHT UNION FOR TUBING	Inspection and acceptance	MA'ADEN WA'AD AL SHAMAL PHOSPHATE COMPANY	Umm Wu'al EPC Project Infrastructure, Utilities & Offsites at Ras Al Khair	2015	
ABB MOTORES	Polígono industrial S.O. // C/ Illa de buda, 55// 08192 Sant Quirze del Vallès Barcelona	ITEM 26E-004 Motor 25 kW – 1200 rpm//480/60/3 ITEM 26E-010 Motor 35 kW – 1800 rpm // 480/60/3	Inspection and acceptance	SACYR	RLP21 ADECUACION A NUEVAS ESPECIFICACIONES DE COMBUSTIBLES BLOQUE DE DESTILADOS MEDIOS	2015	
ABB MOTORES	Sant Sadurni de Noia (Spain)	COKE BRIDGE CRANE	Inspection and acceptance	ERC	ERC project	2015	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	KUWAIT OIL COMPANY K.S.C. (I&C) (KOC)	EF-1894	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	Audit	Inspection and acceptance	China Petroleum Engineering & Construction Corporation (CPEC	IRAQ WEST QURNA 1- PHASE II	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	EMERGENCY M-60	Inspection and acceptance	IBERDROLA		2015	
SAIDI	Masiía del conde, Naves 1-3 Pol. Masía de Baló 4619 Ribarroja del Turia (Valencia)	JC VALVES	Inspection and acceptance	CCIAT OF MEXICO	COGENERACIÓN AFRANRENT	2015	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	Painting, Marking/Nameplate & Packing / Marking.	Inspection and acceptance	GHN	Y06171 / 14319 YIBAL A FWKO PUMP	2015	
SAMSON SA	Avd. Can Sucarrats ,104. 08191 Rubí (Barcelona)	Recambios puesta en marcha según pedido de REPSOL	Inspection and acceptance	SACYR	V0P21-000-J-604-001-IR-002	2015	
SAMSON SA	Avd. Can Sucarrats ,104. 08191 Rubí (Barcelona)	Self operated valves	Inspection and acceptance	IBN SINA	16100 - IBN SINA POLYOXYMETHYLENE PROJECT	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	MECC	Flow lines at NK areas	2015	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	MECC	Flow lines at NK areas	2015	
VALVULAS NACIONAL	Compositor Chopin, 2-4, Polígono Industrial Can Jardí 08191 - Rubí (Barcelona)	FOUNDRY BODY OF SAFETY VALVES	Inspection and acceptance	VATTENFALL	S009008747	2015	
FONDESAL	Collita, 13. P.I. El Molí de la Bastida 08191 Rubí (Barcelona)	Bodies and bonnets castings of ASTM A494 CW6MC (INCONEL 625)	Inspection and acceptance	ADCO	EPC FOR BUHASA SHUAIBA SOUTH ARTIFICIAL (GAS) LIFT	2015	
FONDESAL	Collita, 13. P.I. El Molí de la Bastida 08191 Rubí (Barcelona)	Bodies and bonnets castings of ASTM A494 CW6MC (INCONEL 625)	Inspection and acceptance	ADCO	EPC FOR BUHASA SHUAIBA SOUTH ARTIFICIAL (GAS) LIFT	2015	
SOLER&PALAU INDUSTRIES SLU	Crta. Puigcerda, s/n 17500 Ripoll (Girona) Spain	Axial Fans and Motors for 114-SSH-001, Axial Fans and Motors for 114-SSH-002	Inspection and acceptance	YAMAL LNG	3300 - JSC Yamal LNG Plant EPSCC	2015	
FONDESAL	C/ Collita, 13. P.I. El Molí de la Bastida 08191 Rubí (Barcelona)	Bodies and bonnets castings of ASTM A494 CW6MC (INCONEL 625)	Inspection and acceptance	ADCO	ADH-4112-A1-1316972	2015	
LORK	Molins de Rei	Plastic Material	Inspection and acceptance	TECHNIP IBERIA SPAIN	VARIOUS	2015	
ABB FABRICA DE TRANSFORMADORE S	Ctra. de Madrid, Km. 314 E- 50.012 Zaragoza (Spain)	Transformers and Container	Inspection and acceptance	ACCIONA ENERGIA SA	EL ROMERO	2015	
INOXTORRES	C/ Caseta 16, 08185 Lliça de Vall Barcelona	SILOS SLUDGE AND SCALE	Inspection and acceptance	TAKREER	NORM Handling, Treatment & Disposal Project at BeAAT	2016	
VALVULAS NACIONAL	Compositor Chopin, 2-4, Polígono Industrial Can Jardí 08191 - Rubí (Barcelona)	7 Cuerpos para válvulas modelo 3-5111 & 14 Cuerpos para válvulas modelo 64	Inspection and acceptance	ACCIONA INGENIERIA INDUSTRIAL	BSV-00-QA-IN-NAC-001	2016	
VALVULAS NACIONAL	Compositor Chopin, 2-4, Polígono Industrial Can Jardí 08191 - Rubí (Barcelona)	7 Cuerpos para válvulas modelo 3-5111 & 14 Cuerpos para válvulas modelo 64	Inspection and acceptance	ACCIONA INGENIERIA INDUSTRIAL	BSV-00-QA-IN-NAC-001	2016	
SAMSON SA	Avd. Can Sucarrats ,104. 08191 Rubí (Barcelona)	Self operated valves	Inspection and acceptance	IBN SINA	16100 - IBN SINA POLYOXYMETHYLENE PROJECT	2016	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Purpose
Hidracar Shop	Pol. Ind. Les Vives - c/ Anaïs Nin, 14, 08295 Sant Vicenç de Castellet	11.2 Pulsation Dampener- Hydro test 11.3 Pulsation Dampener- Visual & Dimensional check 11.4 Pulsation Dampener- Name Plate Check	Inspection and acceptance	NORTH YARAN	Yaran North Oil Field Development	2016	
INOXTORRES	Tarragona, Catalunya, E-43800, Spain	SILOS SLUDGE AND SCALE	Inspection and acceptance	ABU DHABI OIL REFINING COMPANY	NORM Handling, Treatment & Disposal Project at BeAAT - Project no. 5640	2016	
COPISA	Tarragona	LPG CAUSTIC TREATER PACKAGE (TQ-31010)	Inspection and acceptance	ICA FLUOR	PEMEX TULA	2016	
INOXTORRES	Tarragona, Catalunya, E-43800, Spain	SILOS SLUDGE AND SCALE	Inspection and acceptance	ABU DHABI OIL REFINING COMPANY	NORM HANDLING, TREATMENT & DISPOSAL	2016	
ABB MOTORES	Illa de Buda, 55 08192 Sant Quirze del Valles	VARIADORES DE VELOCIDAD SOPLANTES 53-VV-GM-202 A/B	Inspection and acceptance	REPSOL	RLP21 ADEQUACIÓ A NOVES ESPECIFICACIONS DE COMBUSTIBLES BLOC DESTIL·LAT MITJANS	2016	
ABB FABRICA DE TRANSFORMADORE S	Ctra. de Madrid, Km. 314 E- 50.012 Zaragoza (Spain)	TRANSORMADORS ELECTRICS DE POTÈNCIA	Inspection and acceptance	ACCIONA ENERGIA SA	EL ROMERO	2016	
SAMSON SA	Avd. Can Sucarrats ,104. 08191 Rubi (Barcelona)	SELF OPERATED VALVES 350-PCV-1010, 350-PCV-0205, 350-PCV-0206-350-PCV-0207	Inspection and acceptance	IBN SINA	16100 - IBN SINA POLYOXYMETHYLENE PROJECT	2016	
SOLER&PALAU INDUSTRIES SLU	Crta. Puigcerda, s/n 17500 Ripoll (Girona) Spain	EXHAUST FAN AND EMERGENCY FAN FOR MODULE 047-PAU-001 NORTH. IMPELLER CONE(FANS) & MOTORS FOR MODULE 111-PAU-001	Inspection and acceptance	YAMAL LNG	3300-LSC YAMAL LNG PLANT EPSCC	2016	
AGUILAR & SALAS	Irlanda 5, Les Franqueses del Vallès - Barcelona E 08520	FILTER VESSELS (SW SUPPLY FILTER LOOP 1/2/3)	Inspection and acceptance	HITACHI INDUSTRIAL ENGINEERING	VALCOM	2016	
EMBALEX S.L.	Templer Guidó , Poligono Industrial Palau 08184 Palau-Solità i Plegamans Barcelona-España	TRANSFORMER ABB 1 LES 33022118	Inspection and acceptance	EMBALEX S.L.	ROMERO CHILE	2016	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	GATE VALVES, BALL VALVES, AIR RELIEF VALVES, CHECK VALVES, BALL VALVE WITH SPINDLE EXTENSION AND GATE VALVE FOR AIR VALVE ISOLATION.	Inspection and acceptance	BP OMAN	KHAZZAN GAS PROJECT	2016	
JC Fabrica de Valvulas SA	SANT BOI DE LLOBREGAT BARCELONA	ESDV-SBDV-BDV VALVES	Inspection and acceptance	KOC	DDP Contract no 12050869	2016	
IBERFLUID INSTRUMENTS S.A	Botànica, 122, 08908 L'Hospitalet de Llobregat, Barcelona	SAMPLE TAKING DEVICES	Inspection and acceptance	INTECSA	IBN SINA POLYOXYMETHYLENE PROJECT	2016	
IBOR VALVES-MECANIZADOS ESFERIMEÇ SL	CARRER MONTSIÀ, 2-8. POL. IND. CAN CARRER 08211 CASTELLAR DEL VALLES (BARCELONA)	VALVES: CHECK VALVES, GATE VALVES AND GLOBE VALVES	Inspection and acceptance	JONDISHAPOUR CO.	HENGAM GAS TREATMENT SYSTEM PROJECT	2016	
GAMOBÉ FOR CABLE S.R.L	SANT PERE, 34. 08711 (ÓDENA)	Pay-off / Take-up (POTU)	Inspection and acceptance	WRI Australia	CM25 Safety Upgrage Project	2016	
TECAM Group / ECLIPSE	OCCITANIA, 58. 08911 - BADALONA	VALVE TRAINS AND BURNERS	Inspection and acceptance	INTECSA	INSPECTION TEST PLAN (ITP) VALVE TRAINS	2016	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	DESCON & ADCO	EPC OF ADCO SAHIL FIELD DEVELOPMENT PROJECT PHASE-2	2016	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
VALVULAS NACIONAL	Compositor Chopín, 2-4, Polígono Industrial Can Jardí 08191 - Rubí (Barcelona)	PRESSURE RELIEF VALVES	Inspection and acceptance	TECNICAS REUNIDAS	HAIL SURFACE FACILITIES EPS PROJECT	2016	
TALLERES ELPA	De les terres blanques, 10. 17740 - VILAFANT (Figueres)	HEAT RECOVERY STEAM GENERATORS	Inspection and acceptance	NOOTER ERIKSEN	UMM AL HOUL POWER PROJECT/SAMSUNG C&T CORP.	2016	
ATTSU TECHNIVAP	POL. IND. C/FALGUERES, S/N 17460 CELRÀ (GIRONA) SPAIN	HEAT RECOVERY STEAM GENERATORS	Inspection and acceptance	NOOTER ERIKSEN	UMM AL HOUL POWER PROJECT/SAMSUNG C&T CORP.	2016	
TECAM Group / ECLIPSE	OCCITANIA, 58. 08911 - BADALONA	VALVE TRAINS AND BURNERS	Inspection and acceptance	INTECSA	INSPECTION TEST PLAN (ITP) VALVE TRAINS	2016	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	VALVES	Inspection and acceptance	RAS AL HAMRA LLC	RABAB HARWEEL POWER PLANT &HRSG PROJECT	2016	
AGUILAR & SALAS	Irlanda 5, Les Franqueses del Vallès - Barcelona E 08520	SOLVENT PREWASH & EXTRACTOR	Inspection and acceptance	ICA FLUOR	PEMEX TULA	2016	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	DODSAL Engineering Procurement & Construction	EPC FOR RUMAITHA / SHANAYEL FACILITIES – PHASE III	2016	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	SEAWATWATER REVERSE OSMOSIS (SWRO) PKG	Inspection and acceptance	ARTES INGEENERIA	Satah Al-Razboot (SARB) Field Development Project – EPC PKG4	2016	
APLICLOR	Afores, S/N, 08282 Sant Martí Sesgueioles, Barcelona	BALL VALVES	Inspection and acceptance	GABAL EL ASFAR	MINISTRY OF HOUSING, UTILITIES AND URBAN DEVELOPMENT (CAPW)	2016	
JC Fabrica de Valvulas SA	Cantabria, 2 – Pol Ind. Les Salines 08830 Sant Boi de Llobregat (Barcelona)	BALL VALVES	Inspection and acceptance	DODSAL Engineering Procurement & Construction	EPC FOR RUMAITHA / SHANAYEL FACILITIES – PHASE III	2016	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	Carmeuse Majan LLC (SFZ)	Gas Supply to Carmeuse Majan at SFZ	2016	
AGUILAR & SALAS	Irlanda 5, Les Franqueses del Vallès - Barcelona E 08520	SEA WATER FILTERS	Inspection and acceptance	SAUDI ARABIAN OIL COMPANY	EPC13 UTILITIES DISTRIBUTION PACKAGE JAZAN REFINERY AND TERMINAL PROJECTS DEPARTMENT	2016	
FIVE PILLARD/ELPA	Pol. Industrial C/Falgueres S/N 17460 CELRA-GIRONA-SPAIN	HEAT RECOVERY STEAM GENERATORS	Inspection and acceptance	Samsung C&T Corp.	UMM AL HOUL POWER PROJECT	2016	
JC Fabrica de Valvulas SA	POL. PALAU INDUSTRIAL, CARRER TEMPLER GUIDO,25, 08184 PALAU-SOLITA I PLEGAMANS, BARCELONA	TRUNNION BALL VALVES	Inspection and acceptance	KSA	NEW HOUT CRUDE TRANSMISSION LINE	2016	
KITZ	Calle Ramon Viñas, 8 Sant Adria de Besos, Barcelona 08930 Spain	TRUNNION VALVE	Inspection and acceptance	SACYR	RLP21 ADECUACION A NUEVAS ESPECIFICACIONES DE COMBUSTIBLES BLOQUE DE DESTILADOS MEDIOS	2016	
IBERFLUID INSTRUMENTS S.A	Botànica, 122, 08908 L'Hospitalet de Llobregat, Barcelona	V-CONE FLOWMETER	Inspection and acceptance	TECNICAS REUNIDAS	HAIL SURFACE FACILITIES EPS PROJECT	2016	
SYSTEM FILTER MEDIAM	Edison, 20 (Pol. Ind. Bufalvent) – 08243 Manresa (Barcelona)	FES BAG HOLDING CAGES	Inspection and acceptance	ARVAND JAHANARA STEEL CO.	ARVAND JAHANARA STEEL COMPLEX STEELMAKING PLANT PROJECT – PHASE I	2016	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	POT BEARINGS	Inspection and acceptance	CGCC	RA-210 (Elastomeric Mechanical Expansion Bearings)	2016	
ECONTROL VALVES	Pol. Industrial Constantí calle Grecia, edificio B4 43120 Constantí, Tarragona	VALVES	Inspection and acceptance	TORC	TEHRAN OIL REFINING COMPANY	2017	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
VALVULAS NACIONAL	Compositor Chopin, 2-4, Polígono Industrial Can Jardí 08191 - Rubí (Barcelona)	SAFETY AND RELIEF VALVES	Inspection and acceptance	SACYR FLUOR	RLP21 ADECUACION A NUEVAS ESPECIFICACIONES DE COMBUSTIBLES BLOQUE DE GASOLINAS	2017	
ARCAMO	Polígon Industrial Riu Clar, c/Del Coure , Parcela 167 43006 TARRAGONA	ENFRIADOR DE MUESTRAS	Inspection and acceptance	PRO-AGROINDUSTRIA S.A. DE C.V.	REHABILITACIÓN DE PLANTAS DE UREA Y OTRAS INSALACIONES AUXILIARES	2017	
HYDAC TECHNOLOGY	Calle Solsones 54 Pol. Ind. Pla de la Bruguera. Castellar del Valles, Barcelona	LUBE OIL	Inspection and acceptance	GE POWER	1230 MW CCPP HAVELI BAHADUR SHAH, PAKISTAN	2017	
V & C IBERICA SL	P.E. Cervelló; C/Xarelo 2; 08758 Cervelló, Barcelona; Spain	BOILER FEED WATER IMPROVEMENT	Inspection and acceptance	SABIC UK Petrochemicals	OLE6 Boiler Feed Water Improvement	2017	
SODECA	Ctra. De Berga, km. 0,7 08580 – Sant Quirze de Besora – Barcelona (Spain)	MHS SUCTION & FILTERING SYSTEM (FANS)	Inspection and acceptance	ARVAND JAHANARA STEEL COMPLEX	ARVAND JAHANARA STEEL COMPLEX STEELMAKING PLANT PROJECT – PHASE I	2017	
CORACI SA	C/Albert Einstein, 52 - Polígono Industrial Almeda - 08940 Cornellá de Llobregat (BARCELONA)	GENERAL ARRANGEMENT AND DIMENSIONAL DRAWING (RUBBER WITH TIE RODS - SINGLE ARCH)	Inspection and acceptance	SAUDI ELECTRICITY COMPANY	DUBA GREEN INTEGRATED SOLAR COMBINED CYCLE POWER PLANT	2017	
SERTEMO	Pol. Ind. L'Alba, Avda. Generalitat, F-102; Ap. Correos 142 43480 VILA-SECA (Tarragona)	FUSIBLE LIINK VALVES	Inspection and acceptance	CUÑADO SA	DUBA GREEN INTEGRATED SOLAR COMBINED CYCLE POWER PLANT	2017	
MAIVISA	Serra Vallmorena 8-10 P.I. Vallmorena II Vilassar de Dalt, Barcelona	REBOILER	Inspection and acceptance	HUNTSMAN PETROCHEMICAL LLC	REBOILER ER-220-1	2017	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	GROUTING PORT	Inspection and acceptance	MUSHRIF TRADING AND CONTRACTING CO. (KSCP) KUWAIT	-	2017	
MONTAJES RUS	C/ Sant Bartomeu, parc. 123 08600 – Berga (Barcelona)	BASKET STRAINERS	Inspection and acceptance	SAUDI ELECTRICITY COMPANY	DUBA GREEN INTEGRATED SOLAR COMBINED CYCLE POWER PLANT	2017	
ABB MOTORES	Polígono industrial S.O. // C/ Illa de buda, 55// 08192 Sant Quirze del Vallès Barcelona	LEAN AMINE BOOSTER PUMP MOTOR	Inspection and acceptance	TECHNIP	EPC WORKS - UMM LULU FULL FIELD DEVELOPMENT (PACKAGE 2)	2017	
APLITEC	CAMI DE LES ARENES, Nº 8 – 10 POL. IND. SANTA ANNA III 08251 SANTPEDOR (BARCELONA)	LAMELLAE	Inspection and acceptance	SADYT-SOHAR	SOHAR INDEPENDENT WATER PLANT	2017	
ATECHBCN	C/Tomás Viladomiu, 29-35 , P.I. Illa 08650 Sallent, Barcelona-Spain	GONDOLA A-25 HAARBA2	Inspection and acceptance	ATECHBCN	GONDOLA A-25 HAARBA2 - ISRAEL	2017	
INGALSA	Pol. Can Buscarons de Baix Carrer Besós 8-10, Montornès del Vallès, Barcelona - 08170	GALVANIZING OF RECTANGULAR TUBES	Inspection and acceptance	UTE GRANSOLAR - ACCIONA INDUSTRIAL - GHELLA	DEWA PHASE III 800 MW PV SOLAR POWER PROJECT	2017	
ARCAMO	Polígon Industrial Riu Clar, c/Del Coure , Parcela 167 43006 TARRAGONA	CONDENSATE POT AND TUBING	Inspection and acceptance	SAUDI ELECTRICITY COMPANY	DUBA GREEN INTEGRATED SOLAR COMBINED CYCLE POWER PLANT	2017	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	POT BEARINGS	Inspection and acceptance	COMBINED GROUP CONTRACTING CO.	RA263	2017	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	POT BEARINGS	Inspection and acceptance	MEKANO4 S.A.	PRO-2160117	2017	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	POT BEARINGS	Inspection and acceptance	PAHW	KUWAIT WW-PR-2160068 SOUTH AL MUTLAA	2017	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
JC Fabrica de Valvulas SA	POL. PALAU INDUSTRIAL, CARRER TEMPLER GUIDO,25, 08184 PALAU-SOLITA I PLEGAMANS, BARCELONA	VAPORIZING EQUIPMENT 720T/H	Inspection and acceptance	KOGAS	INCHEON LNG TERMINAL	2017	
IBOR VALVES-MECANIZADOS ESFERIMEÇ SL	CARRER MONTSIÀ, 2-8. POL. IND. CAN CARRER 08211 CASTELLAR DEL VALLES (BARCELONA)	BALL VALVES – FLOATING & TRUNNION	Inspection and acceptance	DUBAI PETROLEUM	FATEH-FUEL GAS HEATER PROJECT	2017	
AMIANITIT SPAIN SA	POLÍGON INDUSTRIAL LA VENTA NOVA, 91 43894, CAMARLES, TARRAGONA, SPAIN	PIPE, FLANGES AND SPOOLS	Inspection and acceptance	SAMSUNG	ALGERIA NAAMA OR MOSTAGHANEM CCPP PROJECT	2017	
FUTURE PIPE SPAIN	Poligono Industrial Valdeferrin (Cl 3 Parc. 49) 50600 EJEA DE LOS CABALLEROS	COOLING WATER GRP PIPING	Inspection and acceptance	GENERAL ELECTRIC	SERGIPE - BRASIL	2017	
VICAN - STF FILTROS	Pol. Ind. La Armentera, parcela 36 22400 Monzon (Huesca) España	COOLING WATER GRP PIPING	Inspection and acceptance	GENERAL ELECTRIC	UTE PORTO DE SERGIPE	2017	
TRANSMESA SA	POL INDUSTRIAL VALLDEGATA JOAN DRAPER, FOSSAS 30 BARCELONA, SPAIN 08350	SAE J524-91 Carbon SMLS HYD Tubing NBK Grade 1010/1008	Inspection and acceptance	AARIS LLC	INSPECTIONS AT NIMET	2017	
PLANTA DE VAKKUM DE HAM	Carrer Joan Oró, 1, 08635 Sant Esteve Sesrovires, Barcelona	VACUUM-INSULATED TRANSPORTABLE CONTAINERS ON TRUCK	Inspection and acceptance	GASES DEL PACIFICO SAC	VKC101.0_PPI_Cisterna Vacío (Colombía)	2017	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	POT BEARINGS	Inspection and acceptance	MEKANO4 S.A.	RA240	2017	
ECONTROL VALVES	Pol. Industrial Constantí calle Grecia, edificio B4 43120 Constantí, Tarragona	VALVES	Inspection and acceptance	BERNARD CONTROL SPAIN SLU	SP GAS FIELD DEVELOPMENT-PHASES 20&21	2017	
SODIMATE IBERICA SL	C/ Samonta, 6 A Pol. Ind. Font Santa 08970 SANT JOAN DESPI (Barcelona)	LIME DOSING SYSTEM	Inspection and acceptance	SADYT	SOHAR INDEPENDENT WATER PLANT	2017	
CORACI SA	C/Albert Einstein, 52 - Polígono Industrial Almeda - 08940 Cornellà de Llobregat (BARCELONA)	EXPANSION JOINTS	Inspection and acceptance	INTECSA / EL-NASR CO. FOR INTERMEDIATE CHEMICALS (NCIC)	FERTILIZERS COMPLEX IN SOKHNA (FCS)	2017	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	POT BEARINGS	Inspection and acceptance	MEKANO4 S.A.	RA264	2017	
GRUPO TATOMA SL	Polígono Industrial Armentera, 43 22400, MONZON (HUESCA)	INTERIOR GUIDE TUBE, EXTERIOR GUIDE TUBE, CROSSMEMBER	Inspection and acceptance	ThyssenKrupp Airport Systems	ORAN, KUWAIT	2017	
GRUPO TATOMA SL	Polígono Industrial Armentera, 43 22400, MONZON (HUESCA)	INTERIOR GUIDE TUBE, EXTERIOR GUIDE TUBE, CROSSMEMBER	Inspection and acceptance	ThyssenKrupp Airport Systems	Worth TEXAS USA A52425533	2017	
GRUPO TATOMA SL	Polígono Industrial Armentera, 43 22400, MONZON (HUESCA)	INTERIOR GUIDE TUBE, EXTERIOR GUIDE TUBE, CROSSMEMBER	Inspection and acceptance	ThyssenKrupp Airport Systems	PIERRE REGIONAL AIRPORT A52425533	2017	
GRUPO TATOMA SL	Polígono Industrial Armentera, 43 22400, MONZON (HUESCA)	INTERIOR GUIDE TUBE, EXTERIOR GUIDE TUBE, CROSSMEMBER	Inspection and acceptance	ThyssenKrupp Airport Systems	COSTA RICA A52425533	2017	
METALBAME	Pol.Ind.Francoli Parcela 13 B 43006-Tarragona, Spain.	CONDENSER WATER BOX	Inspection and acceptance	AMEC FOSTER WHEELER	SABIYA CCGT-01 (55)	2017	
APLIMET SALA	Carrer Famades, 35. Hospitalet de Llobregat, (08907) Barcelona	SILENCERS	Inspection and acceptance	STOPSON ITALIANA	TOTAL PHOENIX EPsCm	2018	
TECFLUID ESPAÑA	Narcís Monturiol, 33 08960 Sant Just Desvern (Barcelona) España	FLOW INDICATORS	Inspection and acceptance	SADYT	SEA WATER REVERSE OSMOSIS PLANT SOHAR-OMAN	2018	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	SUPORT DEVICES	Inspection and acceptance	SAPTA EPE/SPA	EN-PR-2170203	2018	
PAYPER SA	Pol. Ind. El Segre, parc.115 25191 Lleida (Spain)	AUTOMATIC BAGGING LINES	Inspection and acceptance	INDOFIL INDUSTRIES LTD	MANCOZEB	2018	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Expediting	BECHTEL LIMITED	PENNSYLVANIA CHEMICALS	2018	
TORNILLERIA INDUSTRIAL	Carrer Catalunya Nº 11 P.I. Can Oller, Santa Perpetua de Mogoda, Barcelona, 08130	ANCHOR BOLT	Inspection and acceptance	IEC	SCR Anchor Bolts - STRUCTURAL STEEL for Rutenberg Power Station	2018	
ABB Drives	Polígono industrial S.O, Carrer Illa de Buda, 55, 08192 Sant Quirze del Vallès, Barcelona	PUMPS	Inspection and acceptance	FLOWSERVE	ESCONDIDA WATER SUPPLY EXPANSION PROJECT	2018	
CORACI SA	C/Albert Einstein, 52 - Polígono Industrial Almeda - 08940 Cornellà de Llobregat (BARCELONA)	ELASTOMER EXPANSION JOINTS	Inspection and acceptance	TECHINP	FERTILIZERS COMPLEX IN SOKHNA (FCS)	2018	
MEISA	Carretera T-721 de Constanti a La Pobla de Mafumet Km 1, 843120 – Tarragona – Spain.	Steam Surface Condenser	Inspection and acceptance	POWER STATION PROJECTS	Sabiya CCGT-01 (55)	2018	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	GAS VALVE	Inspection and acceptance	QATARGAS	QG2 and QG3&4 flare reduction project	2018	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Valles (BARCELONA)	POT BEARINGS	Inspection and acceptance	BEARINGS AIRPORT BAHREIN	BIA Airport Modernization Program	2018	
ZAERA	Camí de la Roca s/n -43711 Bayers del penedés	TRUCK WEIGHTBRIDGE	Inspection and acceptance	INTECSA INDUSTRIAL	BeAAT EXPANSION PROJECT / INTECCSA INGENERIA INDUSTRIAL /10441	2018	
PEKOS GROUP	Rec del Molinar nº 9,Pol. Ind. "El circuit" ,, 08160 Montmeló, Barcelona	Surface cjeck and dimensional inpection	Inspection and acceptance	al momoon	TS-17-0367	2018	
EATON-COOPER CRUISE	Avda. Santa Eulalia 290, Vial B, Pab.5 08223 TERRASSA	DISTRIBUTION BOARD	Inspection and acceptance	PETROJET	SIBA FIELD DEVELOPMENT PROJECT	2018	
SCHWARTZ HAUTMONT	Schawartz-hatmant construcciones metálicas Avinguda de la conoja,9 vilaseca	Pressure Vessel	Inspection and acceptance	GALP	7031078936	2018	
MEISA	Carretera T-721 de Constanti a La Pobla de Mafumet Km 1, 843120 – Tarragona – Spain.	Tubos aleteados y paneles de tubos aleteados	Inspection and acceptance	ENDESA GENERACIÓN	CT Litoral	2018	
COLWAY	Camí Can Ubach, Nave 30. Polígono Industrial Les Fallulles Sant Vicenç dels Horts Barcelona 08620 España	Ball Valves	Inspection and acceptance	COLWAY	300 LT RED DE TRANSMISIÓN ASOCIADA AL CC TOPOLOBAMPO III (1812) L.T. / S.E. (obra)	2018	
JC Fábrica de Válvulas SA	C/Cantabria,2 – Polígono Industrial Les Salines 08830 Sant Boi de Llobregat Barcelona (Spain)	2 NO. 20" Valves	Inspection and acceptance	PD&MS Energy (Aberdeen) Ltd	Spirit Energy Project	2018	
MEKANO4 S.A.	P.I. Can Nadal, Can Nadal Nave 1-A 08185 Lliçà de Vall (BARCELONA)	Support devices for the viaduct	Inspection and acceptance	SAPTA EPE/SPA	EN-PR-2160094, WW-PR- 2170486, EN-PR-2170018	2018	
ICORSA	Avda del Valles Nave 6, KM 11 Pol Ind La Serra I 08185 Liça de Vall Barcelona	COMBUSTION SKID FUEL GAS SUPPLY	Inspection and acceptance	Axion Energy Argentina SA	Revamps	2018	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
ARCAMO	Polígon Industrial Riu Clar, c/Del Coure , Parcela 167 43006 TARRAGONA	Sistema analizadores	Inspection and acceptance	Sacyr - Cepsa	1701RA28A-FCC REVAMPING LIGHT ENDSRefinería La Rávida (Huelva)	2018	
BV MK4	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	SUPPLY OF BEARINGS OF VARIOUS SIZES AND SPECIFICATIONS	Inspection and acceptance	MK4 WORLD WIDE S.L.	SOUTH AL MUTLAA UTILITY BRIDGES (STATE OF KUWAIT)	2018	
JC Fabrica de Valvulas SA	POL. PALAU INDUSTRIAL, CARRER TEMPLER GUIDO,25, 08184 PALAU-SOLITA I PLEGAMANS, BARCELONA	FLOATING BALL VALVE	Inspection and acceptance	APPLUS NORCONTROL SLU	Project	2018	
GASSÓ SA	Pol. Industrial Can Calderon Caller Murcia, 35 nave C - Sant Boi de Llobregat (Barcelona)	Tank Wagon Loading Arms	Inspection and acceptance	ANCORE	Tank Wagon Loading Arm	2018	
VALVULAS NACIONAL	Compositor Chopín, 2-4, Polígono Industrial Can Jardí 08191 - Rubí (Barcelona)	RELEASE VALVES	Inspection and acceptance	B & V	ESCONDIDA WATER SUPPLY EXPANSION PROJECT	2018	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Expediting	BECHTEL LIMITED	PENNSYLVANIA CHEMICALS	2019	
BAC VALVES S.A.	Tapis, 126 - P.O. Box 13 17600 Figueres (Girona)	BALL VALVES	Inspection and acceptance	NPCC	EPC WORKS –UMM LULU FULL FILED DEVELOPMENT (PACKAGE 2)	2019	
MEKANO 4 S.A	Ronda de la Font del Carme, s/n, 08193, Bellaterra, Barcelona, España	FRICTION TEST ON PTFE SAMPLE	Inspection and acceptance	CFE(Confederacion Federal de Electricidad)	WW-2180084 LUSAIL PLAZA INFRASTRUCTURE	2019	
TECNOGERMA	IBIS BUDGET SANT ANDREU DE LA BARCA C/ Energia 1 08740 SANT ANDREU DE LA BARCA (BARCELONA)	HESS HYDROMAT HP III, STATIONARY MULTILAYER MACHINE FOR THE PRODUCTION OF PAVERS IN AN ECONOMIC WAY (HESS TYPE HP-III-VA, YEAR OF CONSTRUCTION 2003)	Inspection and acceptance	PT_BETON INTI GUNAR	MACHINE FOR THE PRODUCTION OF CONCRETE PRODUCTS (SECOND HAND)	2019	
ESTRUAGUA WATER TECHNOLOGY	Irlanda 5, Les Franqueses del Vallès - Barcelona E 08520	Compact pre-treatment Unit & Basket Pro Screens	Expediting	TILAL	TILAL CITY PROJECT	2019	
ECOTEC	Carrer d'Esteve Terradas, 37, A, Pol. Ind, 08243 Bufalvent, Barcelona	DESALINATION PLANT	Expediting	FISIA / ABENGOA	SALALAH IWP	2019	
JC Fábrica de Válvulas SA	Av. Segle XXI, nº75 – Pol Ind. Can Calderón 08830 Sant Boi de Llobregat (Barcelona)	CRYOGENIC BALL VALVES	Inspection and acceptance	BLACK & VEATCH	Swan Jetty Topside and Onshore Facilities Project	2019	
MAIVISA	Serra Vallmorena 8-10 P.I. Vallmorena II Vilassar de Dalt, Barcelona	R-210 Reactor Coils	Inspection and acceptance	HUNTSMAN PETROCHEMICAL LLC	US09 Ethyleneamines Plant	2019	
MAIVISA	Serra Vallmorena 8-10 P.I. Vallmorena II Vilassar de Dalt, Barcelona	LLCN COOLER	Inspection and acceptance	CEPSA, Compañía Española de Petróleos S.A.U.	1DD5563A-CEPSA LA RABIDA: Desulfuración de NAFTAS NFR FASE I	2019	
BV MK4	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	Anchor plate ML405	Inspection and acceptance	MK4 WORLD WIDE S.L.	Static load test of anchor plate ML405.	2019	
JC Fábrica de Válvulas SA	Av. Segle XXI, nº75 – Pol Ind. Can Calderón 08830 Sant Boi de Llobregat (Barcelona)	SHUT DOWN VALVE	Inspection and acceptance	MELLITAH OIL&GAS BV	PROVISION OF OILY WATER SYSTEM UPGRADE - SABRATHA PLATFORM	2019	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
IBOR VALVES-MECANIZADOS ESFERIMEÇ SL	CARRER MONTSIÀ, 2-8. POL. IND. CAN CARRER 08211 CASTELLAR DEL VALLES (BARCELONA)	DUAL PLATE CHECK VALVE NPS 8" 600LB & SLAB GATE VALVE OS&Y NPS 4" 600LB	Inspection and acceptance	EPPM	Surface Faciliy EPC services Phase-4 Development Project	2019	
ESTRUAGUA WATER TECHNOLOGY	Irlanda 5, Les Franqueses del Vallès - Barcelona E 08520	MOTORIZED GATE FOR SEWAGE	Inspection and acceptance	COLOMBO MUNICIPAL COUNCIL	Provision of New Gravity Sewers, Force Mains and Pump Stations for Kirulapone Catchment Area For Colombo Municipal Council	2019	
MEKANO 4 S.A	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	ELASTOMERIC BEARINGS	Inspection and acceptance	MEKANO4 S.A.	WW – PR – 210099 AI Sahel	2019	
RIERA NADEU	Polígono Industrial Coll de la Manyà Cal Ros dels Ocells, 1-3 Parcela 8, Nave 1 y 2 08403 Granollers Barcelona - Spain	CENTRIFUGE PACKAGE	Inspection and acceptance	WOOD GROUP AUSTRALIA	KEMERTON LITHIUM PLANT	2019	
RIERA NADEU	Polígono Industrial Coll de la Manyà Cal Ros dels Ocells, 1-3 Parcela 8, Nave 1 y 2 08403 Granollers Barcelona - Spain	CENTRIFUGE PACKAGE SCREEN SCROLL AND PEELER	Inspection and acceptance	WOOD GROUP AUSTRALIA	Albemarle Kemerton Lithium Plant Project	2019	
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	ELASTOMERIC BEARINGS	Inspection and acceptance	EPE SAPTA SPA	WW – PR – 2180313 SAPTA	2019	
ARTLUX EUROPA SL	Parc de Negocis "MAS BLAU" c/Garrotxa, 10 08820 El Prat de Llobregat	SHIPMENT INSPECTION	Inspection and acceptance	DAVIPLUS BERKES	i	2019	
JC Fábrica de Válvulas SA	Av. Segle XXI, nº75 – Pol Ind. Can Calderón 08830 Sant Boi de Llobregat (Barcelona)	MOV and Manual valve order	Inspection and acceptance	Doha Petroleum (Dopet)	QP-ONSAG PHASE 2 Project	2019	
JC Fábrica de Válvulas SA	Av. Segle XXI, nº75 – Pol Ind. Can Calderón 08830 Sant Boi de Llobregat (Barcelona)	MOV valve order	Inspection and acceptance	GALFAR	EPIC for Debottlenecking of QP Gas Grid at RLIC Phase II	2019	
ELECTRA MOLINS SA	Parc de Negocis "MAS BLAU" c/Garrotxa, 10 08820 El Prat de Llobregat	GENERATOR SETS	Inspection and acceptance	PETRONOR	ADI 2569. REPSOL PETROLEO	2019	
TECNOLOGIAS ECONTROL	Calle Grecia, Edificio B4-43120, Constantí (Tarragona) Spain	Butterfly and ball valves	Inspection and acceptance	SSEM	SALINE WATER CONVERSION CORPORATION	2019	
TOSACA	GUIFRE, 791 08918 Badalona (Barcelona), Spain	SAFETY VALVES	Inspection and acceptance	SSEM	Taif-Turbah-Ranyah-Alkhurma WATER TRANSMISSION SYSTEM	2019	
ABB	C/ILLA DE BUDA 55 08192 SANT QUIRZE DEL VALLES BARCELONA	MOTOR VARIADOR	Inspection and acceptance	REPSOL PETRÓLEO, S.A	“CAMBIO DE MOTOR CON VARIADOR DE LA BOMBA DE GASOIL PESADO (Pump-around) 655-P-1308-A”	2019	
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	Post-tensioning kits for prestressing structures	Inspection and acceptance	Egipto	PR – 2160003	2019	
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	Bridge POT guided	Inspection and acceptance	EGYPTO	PR – 2160003	2019	
KITZ	Calle Ramon Viñas, 8 Sant Adria de Besos, Barcelona 08930 Spain	NITROGEN GENERATION PACKAGE	Expediting	PETROFAC INTERNATIONAL	Qusahwira	2019	
ELECTRAMOLINS	Camí Can Ubach, Nave 14, Sant Vicenç dels Horts Barcelona 08620 España	0,38kV EMERGENCY DIESEL GENERATOR	Inspection and acceptance	BESIX	SWRO PLANT IN JEBEL ALI POWER STATION	2019	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Purpose
TECNOLOGIAS ECONTROL	Calle Grecia, Edificio B4-43120, Constantí (Tarragona) Spain	Butterfly and ball valves	Expediting	SSEM	SALINE WATER CONVERSION CORPORATION	2020	
TECNOLOGIAS ECONTROL	Calle Grecia, Edificio B4-43120, Constantí (Tarragona) Spain	Butterfly and ball valves	Inspection and acceptance	SSEM	TAIF-TURUBAH / RANYAH / AL KHURMAH WATER TRANSMISSION SYSTEM – BALL & BUTTERFLY VALVES	2020	
ELECTRA MOLINS S.A.	Camí Can Ubach, Nave 14, Sant Vicenç dels Horts Barcelona 08620 España	Emergency diesel generator	Inspection and acceptance	Dubai electricity	P03761800009-L-01-E-R-01900	2020	
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	Bridge POT guided	Inspection and acceptance	Ministry of public works, state of kuwait (MPW)	RA-210 (Elastomeric Mechanical Expansion Bearings)	2020	
TECNOLOGIAS ECONTROL	Calle Grecia, Edificio B4-43120, Constantí (Tarragona) Spain	Butterfly and ball valves	Inspection and acceptance	SSEM	TAIF-TURUBAH / RANYAH / AL KHURMAH WATER	2020	
ASESORIA TECNICA Y CONTROL	Av corts catalanes, 2, 08173 Sant Cugat del Vallès	Air Diffuser system	Inspection and acceptance	ORASQUALIA	Abu Rawash WTP – Cairo, Egypt	2020	
PEKOS VALVES S.L.U	Rec del Molinar, 9, Poligono E-08160 Montmelo Barcelona - SPAIN	Ball Valve	Inspection and acceptance	SEI	SSTPC 260KTA/Y POLYCARBONATE	2020	
MUZAMI CONTRATAS, SL	Sant Andreu de la Barca	Unidades Pasamuros	Inspection and acceptance	UTE EDAR VILAFRANCA	EDAR VILAFRANCA	2020	Visual and dimensional inspection of bushing wall, welding cleanliness
SABO ESPAÑOLA	P.L. Can Cuyás-C/Arquitectura, 14, Nave 7 08110 Montcada i Reixac (Barcelona)	FIRE FIGHTING ITEMS	Inspection and acceptance	TYCO LIMITED OMAN		2020	
CASALS CARDONA INDUSTRIAL SA	Ferran Casablanques, 24 Manresa 08243	PTFE Centrifugal pump (Fluoroplastics)	Inspection and acceptance	SEI	HUAYOU LIHUA (HONG KONG)	2020	
MAIVISA	Serra Vallmorena 8-10 08339 Vilassar de Dalt	Heat Exchanger	Inspection and acceptance	German tyssen	KXEO-01100 NCIC Ain Sohkna	2020	Tube sheet weld, NDT, dimensional inspection and pressure test
ESTRUAGUA WATER TECHNOLOGY	CrtaGranollers-Cardedeu,km-1.5,Pol.,Ind.El.Ramassar085 0 Les Franqueses,del Valles, Barcelona - SPAIN	Lamella Clarifier and FST Secondary Clarifier Mechanism	Expediting	PUBLIC WORKS AUTHORITY	WATER TREATMENT PLANT	2020	Delivery of Circular Clarifier Mechanism for WABAG
FONDESAL	Les Planes nº1 Nave B, 08970 Sant Joan Despí (Barcelona)	Impeller	Inspection and acceptance	General Electrics	KEPPEL-ELECTRIC. MERLIMAU	2020	ITP Steps, Visual, penetrant and radiographic examination on prototype
FONDESAL	Collita nº13, 08191 Rubí (Barcelona)	Impeller	Inspection and acceptance	General Electrics	KEPPEL-ELECTRIC. MERLIMAU	2020	Heat treatmen on impeller
CONTRATOS Y DISEÑOS INDUSTRIALES	C/Guifre 799, 08918 Badalona (Barcelona)	Combustion gas Skid	Inspection and acceptance	SEI	Combustion skid for H-61200 & H-81200 Heaters	2020	Hydristatuc test fir gas Skid
EFICIENCIA Y TECNOLOGÍA, S.A.	Bellvei 41-49 , nave 9 – P.I. Can Salvatella 50 08210 Barberá del Vallés	HFFS pouches machine	Inspection and acceptance	Effytec		2020	Kick Off meeting
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	ELASTOMERIC BEARINGS	Inspection and acceptance	EPE SAPTA SPA	WW – PR – 2180313 SAPTA	2020	Dimensional and visual inspection of elastomeric bearings
Aguilar y Salas	Pol.Industrial Pla de Lieronarlrlanda,608520	0502 RECYCLE GAS COMPRESSORS	Inspection and acceptance	SINOPEC-SABIC	PC CHINA PROJECT	2020	Dimensional inspection and hidraulic test
ARCAMO	Polígon Industrial Riu Clar, c/Del Coure , Parcela 167 43006 TARRAGONA	Mounting Accessories Material	Inspection and acceptance	BAPCO	BAPCO MODERNIZATION PROGRAM (BMP)	2020	Visual inspection for Mounting Accessories
SOLER&PALAU INDUSTRIES SLU	Crta. Puigcerda, s/n 17500 Ripoll (Girona) Spain	For GBS1 & GBS2 - Extract & Purge Fans	Inspection and acceptance	ARTIC LNG	079322C – ARCTIC LNG2	2020	Dimensional, performance, noise and vibration test, according to ISO-5801 / AMCA-210 and ISO 14695:2003
CONTRATOS Y DISEÑOS INDUSTRIALES	GUIFRE, 791 08918 Badalona (Barcelona), Spain	Combustion gas Skid	Inspection and acceptance	WOOD PLC	SSTPC PC PROJECT	2020	Piping Skid Assembly for 2 skid of gas heater

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
MAIVISA	Serra Vallmorena 8-10 08339 Vilassar de Dalt	Cooler condenser and tail gas heater	Inspection and acceptance	German tyssen	KXEO-01100 NCIC Ain Sohkna	2020	Tube sheet weld, NDT, dimensional inspection and pressure test
Soldtek Aplicacions Tecniques S.L.L.	PI Empordà Internacional Av Europa 29 17469 VILAMALLA	Combustion Skid FUEL GAS	Inspection and acceptance	FIVES PILLARD	OPC F19002330	2020	Penetrant, radiographic, and hydraulic test. Dimensional test of combustion skid following: NF EN 13480 (2017) ASME section IX (2017) NF EN ISO 5817 (2007), Classe C/Level C, NF EN ISO 17636-1 (2013) & NF EN ISO 3452-1 (2013)
WIKAWIKAC	Josep Carner, 17, 08205 Sabadell (Barcelona)	PREASSURE GAUGE	Inspection and acceptance	INTECSA & INITEC	SULPHURIC ACID PLANT,SAP U	2020	Dimensional control off 10% of the items, and review of FAT
FONDESAL	Les Planes nº1 Nave B, 08970 Sant Joan Despí (Barcelona)	Impeller	Inspection and acceptance	General Electrics	KEPPEL-ELECTRIC. MERLIMAU	2020	ITP Steps, Visual, penetrant and radiographic examination on prototype according th the standard EN1371-1
Novenco AS	Òptica, 13 nau 7, Polígon Industrial Santa Rita, 08755 Castellbisbal, Barcelona	Centrifugal Fans	Inspection and acceptance	BW LNG	BW TATIANA FSRU	2020	
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	ELASTOMERIC BEARINGS	Inspection and acceptance	EPE SAPTA SPA	WW – PR – 2180313 SAPTA	2020	Dimensional and visual inspection of elastomeric bearings
JC Fábrica de Válvulas SA	Av. Segle XXI, nº75 – Pol Ind. Can Calderón 08830 Sant Boi de Llobregat (Barcelona)	Actuator for Valves	Inspection and acceptance	RINA	SABRATHA PLATFORM -OILY WATER SYSTEM UPGRADE	2020	Functional test and dimensional of valve actuator
PRESCAD	CAMI DE CAN BALLUS, 129B – POL. IND. LA VALLDAN – 08600 BERGA - BARCELONA	"Y" FILTERS	Inspection and acceptance	FLUOR LIMITED	QUELLAVECO PROJECT	2020	Visual and dimensional inspection of Y filters
BRAIDING MACHINES SL	Pol Industrial SANTA ANNA I 11111 Alumini 15, Santpedor Spain	Brained Machine	Inspection and acceptance	GARWARE TECHNICAL FIBRES LIMITED	Chartered Engineering Inspection	2020	Dimensional inspection to verify the spindle stich
RIERA NADEU	Polígono Industrial Coll de la Manya Cal Ros dels Ocells, 1-3 Parcela 8, Nave 1 y 2 08403 Granollers Barcelona - Spain	Wash Centrifuge	Inspection and acceptance	Roche	MASSE	2020	Expediting of the matertrial for the FAT test
ESTRUAGUA WATER TECHNOLOGY	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	SAND WASHER and LONGITUDINAL BRIDGE	Inspection and acceptance	WABAG	Al Kharj Road Sewage Treatment Plant Phase III - 26P28	2020	Visual and dimensional inspection of the SAND WASHER and LONGITUDINAL BRIDGE
Soldtek Aplicacions Tecniques S.L.L.	PI Empordà Internacional Av Europa 29 17469 VILAMALLA	Combustion Skid FUEL GAS	Inspection and acceptance	FIVES PILLARD	OPC F19002330	2020	
FRAPONT	Ciutat d'Asunción, 32 08030 Barcelona T	Acustic Panels	Inspection and acceptance	Permasteelisa S.p.A.	GES-2-MOSCOW	2020	Supervision of the assembly of the acustic panels, the dimensional and the painting procedures according to the PO
ESTRUAGUA WATER TECHNOLOGY	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	LONGITUDINAL BRIDGE	Inspection and acceptance	KRUGER VEOLIA	Limassol West WWTP, Cyprus	2020	
EATON-COOPER CRUISE	Avda. Santa Eulalia 290 08223 Terrassa (Barcelona)	Welding ald lighting Ex e junction box	Inspection and acceptance	QATAR GAS	D6978: NORTH FIELD PRODUCTION SUSTAINABILITY	2020	Visual and dimensional checks and verification of marking, review of the documentation and final documentation
JC Fábrica de Válvulas SA	Av. Segle XXI, nº75 – Pol Ind. Can Calderón 08830 Sant Boi de Llobregat (Barcelona)	Floating Ball VALVE	Inspection and acceptance	REPSOL PETRÓLEO, S.A	Petronor FLUE GAS PARTICULATE REDUCTION PROJECT	2020	Leak test, hidrostatic test, visual inspection and general condition of the valves, it has been done the visual inspection before the disassembly of the valve.
SOLDTEK Aplicacions Tecniques S.L.L.	PI Empordà Internacional Av Europa 29 17469 VILAMALLA	Heating Set	Inspection and acceptance	FIVES PILLARD	OPC F19002330	2020	Visual, dimensional and pneumatic test and the measurement of paint thickness of both items, review the weldings according to ASME IX

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
ESTRUAGUA WATER TECHNOLOGY	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	LAMELLA CLARIFIER	Inspection and acceptance	WABAG	Design and build rehabilitation of DOHA south sewage treatment	2020	
ESTRUAGUA WATER TECHNOLOGY	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	LONGITUDINAL BRIDGE	Inspection and acceptance	KRUGER VEOLIA		2020	
PEDRO GIL	Salvador Albert io Riera, 9 Poligono Industrial Vallmorena, 08339 Vilassar de Dalt, Barcelona	Air Blower for water treatment	Inspection and acceptance	UTE SYMISA-HERCE	PROYECTO CONSTRUCTIVO AMPLIACION DE LA E.D.A.R DE VALDARACETE	2020	Functional test, equilibrate of the motor, assembly of the silent blocks silencers... dimensional control, review of documents
ESTRUAGUA WATER TECHNOLOGY	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	Circular decanting bridge lodon	Inspection and acceptance	WABAG	Al Kharj Road Sewage Treatment Plant Phase III - 26P28	2020	Material certificate, motor and gearbox. Welding procedure especification, visual inspection, penetran test of the welds, dimensional control and review of final documentation
CEI		LAMELLA CLARIFIER	Inspection and acceptance		Design and build rehabilitation of DOHA south sewage treatment	2021	Final inspection of the lamella clarifier,
DRAC DT ENGINYERS	Camí Sant Bartomeu, 66C 08600 Berga, Barcelona	BASKET STRAINERS	Inspection and acceptance	IBERDROLA	CCC TAMAZUNCHALE 2	2021	Hydraulic test for filters of the basket strainers, dimensionals and check for the tag labels of the valve.
BAC VALVES S.A.	Tapis, 126 P.O Box. 13, Figueres, 17600	MANUAL VALVES	Inspection and acceptance	Technip FMC	BP MAURITANIA TORTUE PHASE II	2021	Hydrostatic and high pressure testig of manual valves seat and shell, according to test procedure DP-PRB78-PTP-00
IBOR VALVES	Montsià. 2 08211 Castellar del valles, Barcelona	Complete valves with actuators, Ball Valves, Replacement valve trims actuators and repair kits	Inspection and acceptance	Yamal SPG	Yamal SPG project	2021	Inspection and testing of the valves
GASSÓ SA	Can Calderón, Carrer de Múrcia, 35, 08830 Sant Boi de Llobregat, Barcelona	Sulfuric loading arm	Inspection and acceptance	REKIND	Jambaran Tiung Biru Project / 171612	2021	Hydrostatic test of the loading arm, dimensional control and review of the documents, also it has been done the functional test, using a GAD, of the envelop movements, parking zone and loading zone
GASSÓ SA	Can Calderón, Carrer de Múrcia, 35, 08830 Sant Boi de Llobregat, Barcelona	Sulfuric loading arm	Inspection and acceptance	PEPC	Jambaran Tiung Biru Project / 171612	2021	Hydrostatic test of the loading arm, dimensional control and review of the documents, also it has been done the functional test, using a GAD, of the envelop movements, parking zone and loading zone
Aguilar y Salas	Pol.Industrial Pla de Lieronarlranda,608520	Vacuum Condenser	Inspection and acceptance	Mitsubishi Heavy Industries Engineering, LTD	Ghorasal Polash Urea Fertilizer Project	2021	It has been verify the mounting problem with pipes, and the review of the revision of the drawings
CONTAGAS	Fra Juníper Serra 91-93 08030 Barcelona, Spain	Pressure Transmitter and manifold	Inspection and acceptance	Faramowj Pooya	Persian Gulf Bid Boland Gas Treating	2021	It has been done the final inspection of the pressure transmitter and manifold, according to the ITP it has been done the inspection of the visual and dimension, review of the coduments and name plates
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	Bearing Pots	Inspection and acceptance	Sayed Kadhém Aldurazi & Sons Group	Bridge at umm al saad avenue	2021	Final inspection of the bearing pots, it has been verify the dimensions according to the GAD, it has been verify the construction and the review of the materials certificates
INDUSTRIAS ELÉCTRICAS SOLER S.A	C/ Torrent dels lledoners 128, Canet de Mar (08360), Barcelona (Spain)	Seal Steam Electrical Heater with denomination RXPG 500kW 3~400V 20" 300Lb and TAG 21MAW02AC001	Inspection and acceptance	MYTILINEOS S.A.	Agios Nikolaos – IPP II	2021	Final inspection of the seal steam, it has been done the connection of power stages, the power control measuring the resistance of the stages, the insulation control and the visual and dimension control of the piece, also it has been verify the control panel.

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
SOLDTEK Aplicacions Tecniques S.L.L.	PI Empordà Internacional Av Europa 29 17469 VILAMALLA Espane	HP Pump skid	Inspection and acceptance	FIVES PILLARD	POK	2021	Visual and dimensional ispection of the pump skid parts, stem circuit and fuel circuit, hydrostatic test and review of the documents
EATON-COOPER CRUISE	EATON Terrassa Barcelona, Spain	Switch board anddistribution board	Inspection and acceptance	AUDEX	BPGIC FUJAIRAH TERMINAL - PHASE 2	2021	Visual inspection, explosion proof certificate verification check, general arrangement internal layour and component arrangement, conforming to approved drawings
ESTRUAGUA WATER TECHNOLOGY	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	Grit and Grease removal bridge LONGBRI and Decanter circular LODON	Inspection and acceptance	WABAG	Al Kharj Road Sewage Treatment Plant	2021	Visual inspection and dimensional of the LONGBRI and LODON
PERFORMANCE IN LLIGHTING	poligono industrial 'La llana' P.I LA LLANA C/Pont de Can Claveri,(08191 RUBI (Barcelona)Espana		Expediting	Jacobs Engineering SA	MV/LV TRANSFORMER	2021	Expediting of the material for 2 PO order from CEGELEC and PROLIGHT
AGUILAR I SALAS	Pol.Industrial Pla de LieronaiIrlanda,608520	Crude Wash Column	Inspection and acceptance	CHEMATUR ENGINEERING		2021	Visual inspection, dimensional and review of the documents of 3 crude wash column
VALVULAS NACIONAL S.A	Compositor Vivaldi, 2-8 - P. Ind. "Can Jardi" - 08191 RUBI (Barcelona – Spain)	Safeti Valves	Inspection and acceptance	ENI PROGRETTE	AREA POZZO MONTE ALPI 4x	2021	Set Pressure test according to the standard ASME section VIII, div.1 UG-136(d)(4), Tightness test in bellows (N/A) according to the standard API STD 527 and visual and dimensions check of the valves
AGUILAR I SALAS	Pol.Industrial Pla de LieronaiIrlanda,608520	Heat Exchanger	Inspection and acceptance	FLUOR LIMITED	PEMEX ALKY PLUS	2021	Visual inspection, dimensional and PMI test of 2/4 heat exchanger tubesheet
E+M1156+A1147:P114 7+A1147:K1147	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	Grit and Grease removal Decanter circular LODON	Inspection and acceptance	WABAG	Al Kharj Road Sewage Treatment Plant	2021	Visual inspection and dimensional of and LODON
PEKOS VALVES S.L.U	Montmelo, Barcelona	Manual valves 10"-150#	Inspection and acceptance	QATAR PETROLEUM	STOCK MATERIALS	2021	Dimensional Control, functional test, material certificates & test report review
IBERFLUID INSTRUMENTS S.A	Carrer de la Botanica, 122 08908 Hospitalet de Llobregat	Cooling and Sampling system	Inspection and acceptance	Tecnimont S.P.A	KALLO – Belgium	2021	Final inspection of the samples hydrostatic test and project documentation that it has been mising on the first inspection
ESTRUAGUA WATER TECHNOLOGY	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	Grit and Grease removal Decanter circular LODON	Inspection and acceptance	WABAG	Al Kharj Road Sewage Treatment Plant	2021	Visual inspection and dimensional of and LODON
AGUILAR I SALAS	Pol.Industrial Pla de LieronaiIrlanda,608520	Pressure Vessel	Inspection and acceptance	PAKISTAN REFINERY LIMITED		2021	Dimensional and visual control after the heat treatment, it has been review the ultrasonic and radiographic test report and other NDT reports
AMANCI SALA SA		Unit 216 Renegeration ags heaters	Inspection and acceptance	ILF/SGC-OC	20343756 – BOYSUN	2021	Painting test on the piping structure and fuel skid, thickness of the paint and painting procedure review
LGA TECHNOLOGICAL CENTER	Ronda de a Font del Carme S/N 08193 BELLATERRA	Lifting inserts studs M98	Inspection and acceptance	BV Exploiation	PARC EOLIEN EN MER DE FECAMP	2021	It has been done the tensile strenght test to the break of the lifting insert studs M98
ESTRUAGUA WATER TECHNOLOGY	Pol. Ind. El Ramassar, Carretera de Granollers a Cardedeu km 1.5 08520 Les Franqueses del Valles Barcelona, Spain	Grit and Grease removal bridge LONGBRI and Decanter circular LODON	Inspection and acceptance	WABAG	Al Kharj Road Sewage Treatment Plant	2021	Visual inspection and dimensional of the LODON

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	Bearing Pots	Inspection and acceptance	The arab contractor & elsewedy electric for TANROADS ENGINEERING CONSULTING UNIT (TECU) Ministry of works Tanzania	Julius Neyerere Hydropower project	2021	Final inspection of the bearing pots, it has been verify the dimensions according to the GAD, it has been verify the construction and the review of the materials certificates, it has been done a compression proof load test with satisfactory result
AGUILAR SALAS TORRES SL	Carrer d'Irlanda, 6, 08520 Barcelona	Pressure Vessel 204F	Inspection and acceptance	PAKISTAN REFINERY LIMITED	204-F	2021	It has been done the hydrostatic test of the sample according to the acceptance cryteria of the ASME VIII Div 1.2019 Ed, Also it has been done the pneumatic and the thickness certificate
TECNIUM CASALS CARDONA SA	Ferran Casablanclas, 24 Manresa, Barcelona 08243, Spain	Scrubber, naoh tank, gas extraction blower, re circulation pump	Inspection and acceptance	Grupa Azoty	POLIMERY POLICE PROJECT [EGAT]	2021	It has been done the dimension and visual inspection of the items, for the NaOh tank it has been done the full static leak test
Engineering Fluid Solutions SL (TOSACA)	Carrer de Guifré, 791, 08918 Badalona, Barcelona	SHUT DOWN VALVE	Inspection and acceptance	Saline Water Conversion Corporation	NSPWTS	2021	It has been done the ultrasonic test and the hydrotest of the samples selected, it has been done according to the standard EN4126, also it has been done the test of set pressure and the leak test
JC Fábrica de Válvulas SA	Av. Segle XXI, nº75 – Pol Ind. Can Calderón 08830 Sant Boi de Llobregat (Barcelona)	Shut DOWN VALVE	Inspection and acceptance	OIEC	NGL 3100 Project	2021	It has been done the visual inspection of the shut off valves, also it has been done the functional test and seat leakage test according to the procedure MBE-NGL-BAD-0016-D1
VICAN	Pol Industrial Armentera, Parcela 87, s/n 22400 Monzón, Huesca	Dismantling Joing 44"	Inspection and acceptance	SSEM	Al Qunfudah New City Feeder Water Transmission System	2021	In the first inspection it has been done the hydrostatic test of the valve, the second day has been done the paint control and final inspection
ICORSA	Avda del Valles Nave 6, KM 11 Pol Ind La Serra I 08185 Liça de Vall Barcelona	Unit 216 Regeneration Gas Heaters	Inspection and acceptance	WOOD PLC – AMEC FOSTER WHEELER	20343756 – BOYSUN	2021	Cleaness & item identification, final dossier, functional test and review of technical passpot of the instruments of regeneration gas heater.
VALVULAS NACIONAL S.A	Compositor Vivaldi, 2-8 - P. Ind. "Can Jardí" - 08191 RUBI (Barcelona – Spain)	Safeti Valves	Inspection and acceptance	Saudi Basic Industries Corporation	SABIC Saffron B 10,000 MT Polyetherimide Project	2021	It has been done the hydrostatic test of one sample of each size according to the procedure N51-M0016-PR-R-003
MEKANO4 S.A.	C/ Can Nadal, Nave 1-A Llica del Valles 08185 (Barcelona) Spain	Bearing Pots	Inspection and acceptance	SAPTA EPE/SPA	Ligne miniere	2021	Final inspection of the bearing pots, it has been verify the dimensions according to the GAD, it has been verify the construction and the review of the materials certificates, it has been done a compression proof load test with satisfactory result
COVESTRO SL	Poligono Quimico Sur C.tra Vilaseca La Pineda TV-3148 43110 La Canonja Tarragona, Spain	Vessel, spool, piping and steel structure	Inspection and acceptance	SUEZ WATER TECHNOLOGIES AND SOLUTIONS	QATAR PROJECT 2	2021	It has been inspected the open ISSUES on the pressure vessel.
JC Fábrica de Válvulas SA	Av. del Segle XXI, 75, 08830 Sant Boi de Llobregat, Barcelona	Ball Valve 6060 and Ball valve 515B	Inspection and acceptance	BITHERM SISTEMAS SA	82263	2021	It has been done the inspection of the ball valves, has been done the hydraulic pressure test of the shell and seats, and the pneumatic test with air of the seats
CIRCUTOR (LIFASA)	Valles 32 08130 Santa Perpètua de Mogoda - Barcelona	13,8 kV SWGR Bus-1 / 0,5MVAR	Inspection and acceptance	SSEM	KHOBAR TO DAMMAM / JAMIAG WATER TRANSMISSION SYSTEM WTS PROJECT	2021-2022	It has been done the visual and dimensional test, with this test has been verify the label of the capacitor and the verification of the wiring, it has been done the review of the capacitor certificates routine test report

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Purpose
QUIFER ACTUATORS	C/ Niià Km 8,5, 17600 Figueres, Girona	Control gabinets for pneumatic actuators	Inspection and acceptance		WO-6896	2021	it has been done the final inspection of the cabinets, it has been done the dimension check of 3 of each sample type. Additionally has been done the functional test, the control cabinet operation test and the leakage test
VALVULAS NACIONAL S.A	Compositor Vivaldi, 2-8 - P. Ind. "Can Jordi" - 08191 RUBI (Barcelona – Spain)	Safeti Valves	Inspection and acceptance	NQTET ALABOUR GENERAL TRADING Co LTD	Ministry of Oil/Midland Refineries Co. Daura-Baghdad	2021	It has been done the hydrostatic test of one sample of each size according to the procedure N51-M0016-PR-R-003
CALAF INDUSTRIAS	Isaac Newton, 2 08280 – CALAF, BARCELONA			EDAR VILAFRANCA	E.D.A.R. Vilafranca: am-pliació i millores en la capacitat de reducció de nutrients	2021	It has been done the final inspection of the 3 equipments, has been check the certifactes and also has been done the functional test, dimensional, tag control and paint inspection
SCHWARTZ HAUTMONT	Avenida de la Canonja 9 48480 Vilaseca - Spain	Buffer Tank	Expediting	SICIM	SICIM SAUDI ARABIA	2021	It has been done the dimensional and visual examination of the pressure vessel buffer tank
PEKOS VALVES, S.L.U.	Rec del Molinar, 9 E-08160 Montmeló (Barcelona)	BALL VALVES	Inspection and acceptance	Amec Foster Wheeler Iberia S.L.	RAIZEN PQ2024 EPC	2021	It has been done the inspection of the marking, actuator assembly, dimensional control, functional test and the review of the material certificate
VALVULAS NACIONAL	Compositor Vivaldi, 2-8 - P. Ind. "Can Jordi" - 08191 RUBI (Barcelona – Spain)	SAFETY-RELIEF VALVES	Inspection and acceptance	CTCI Singapore PTE. LTD	SABIC Saffron B 10,000 mt Polyethe-rimide project	2022	It has been done the set pressure test and the tightness test of the safety relief valves, additionally has been done the dimensional test and the review of the certificates
WIKA	Instrumentos WIKA SAU C/ Josep Carner, 11-17 08205 Sabadell (Barcelona) Spain	THERMOCOUPLES/ THERMOWELLS/ PRESSURE GAUGES GAUGES216-01-FA-01 & 216-02-F-01	Inspection and acceptance	WOOD PLC-AMEC FOSTER WHEELER	RFQ №0DE-3380A rev4 dd. 23/07/2020 - ADDITIONAL AGREEMENT1_CONTRACT _BOGPZ-20/195-AFW	2022	It has been done the final inspection of the thermocouples / Thermowells / Pressure gauges, it has been review the material certificate, the calibration certificate, hydrostatic test certificate, PMI, conformity to ATEX directives, certificate of conformity and dimensional control. Packing of the items, final quality dossier
PEKOS	Rec del Molinar, 9 E-08160 Montmeló (Barcelona)	Tank bottom Valve	Inspection and acceptance	CTCI Singapore PTE. LTD	SABIC Saffron B 10,000 MT Polyetherimide Project	2022	It has been done the functional test, visual and dimension examination, marking and identification and document review of the tank valves
AGUILAR I SALAS	Pol. Industrial Pla de Llerona Irlanda, 6 – CP 08520 - Les Franqueses del Vallès, Barcelona (Spain)	Shell & Tube Heat Exchangers	Inspection and acceptance	SABIC UK Petrochemicals	Teesside Improvement Project	2022	Expediting report and verification of Open issues with the vendor
MK4	Lliça de Vall (Barcelona, Spain)	Spherical Pots	Inspection and acceptance		TUBLI BAY WATER FLUSHING IMPROVEMENT	2022	Final inspection on bearing pots, dimensional, paint control and material certificate review
VALVULAS NACIONAL	Compositor Vivaldi, 2-8 - P. Ind. "Can Jordi" - 08191 RUBI (Barcelona – Spain)	SAFETY-RELIEF VALVES	Inspection and acceptance	Nedsa BV	Bushehr Petrochemical Complex Olefin Plant	2022	It has been done the set pressure test and the tightness test of the safety relief valves, additionally has been done the dimensional test and the review of the certificates
SCHNEIDER MADRID		16 units USS 5-1 to 16 and one BDM USS 5a	Inspection and acceptance			2022	Verification of defects on the items
MK4	Lliça de Vall (Barcelona, Spain)	Bearing Pots	Inspection and acceptance		4TH BRIDGE – IRAQ	2022	Final inspection on bearing pots, dimensional, paint control and material certificate review

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Purpose
APPLUS TECNOLOGICAL CENTER IN LGAI TECNOLOGICAL CENTER CAMPUS MK4	Carrer de la Font del Carme, 08193 Cerdanyola del Vallès, Barcelona	Spherical Bearings	Inspection and acceptance	Ministry of works - municipality affairs and urban planning	AL FATEH HIGHWAY UPGRADE	2022	It has been done the Proof load test, the horizontal force capacity test and friction test of the spherical bearing
MODINE GUADALAJARA		16 units USS 5-1 to 16 and one BDM USS 5a	Inspection and acceptance			2022	
APPLUS TECNOLOGICAL CENTER IN LGAI TECNOLOGICAL CENTER CAMPUS UAB	Carrer de la Font del Carme, 08193 Cerdanyola del Vallès, Barcelona	Stud M98x6	Inspection and acceptance	BV France	PARC EOLIEN EN MER DE FECAMP	2022	It has been done the traction test of the stud, yield test and elongation verification
VALVULAS NACIONAL	Compositor Vivaldi, 2-8 - P. Ind. "Can Jardi" - 08191 RUBI (Barcelona – Spain)	Criogenic Valves	Inspection and acceptance	Nedsa BV	Bushehr Petrochemical Complex Olefin Plant	2022	It has been done the set pressure test and the tightness test of the safety relief valves, additionally has been done the dimensional test and the review of the certificates
AGUILAR I SALAS	Pol. Industrial Pla de Llerona Irlanda, 6 – CP 08520 - Les Franqueses del Vallès, Barcelona (Spain)	WASTE WATER SUMP TANK	Inspection and acceptance	Worley Services UK Limited	SPEAR Geleen Plant Balance of Plant EPCm Project	2022	Hydrostatic test of the shell and verification of production stage of the WASTE WATER SUMP TANK
AGUILAR I SALAS	Pol. Industrial Pla de Llerona Irlanda, 6 – CP 08520 - Les Franqueses del Vallès, Barcelona (Spain)	STORAGE TANK & TAC Oil QA TANK / TAC Oil Specification Tank	Inspection and acceptance	Worley Services UK Limited	SPEAR Geleen Plant Balance of Plant EPCm Project	2022	Verification of production stage of the Storage Tank and TAC Oil QA TANK and TAC Oil OFF specification Tank
IES SOLER	Torrent dels lledoners 128, 08360 Canet de Mar (Barcelona)	ELECTRICAL IMMERSION HEATERS	Inspection and acceptance	MAYNILAD	150 MLD LAGUNA LAKE WATER TREATMENT PLANT	2022	Hidrostatic test of the equipment and review of the material certificates
VALVULAS NACIONAL	Compositor Vivaldi, 2-8 - P. Ind. "Can Jardi" - 08191 RUBI (Barcelona – Spain)	SAFETY-RELIEF VALVES	Inspection and acceptance	Nedsa BV	Bushehr Petrochemical Complex Olefin Plant	2022	It has been done the set pressure test and the tightness test of the safety relief valves, additionally has been done the dimensional test and the review of the certificates
COMERCIAL CATALANA DE MAQUINARIA TEXTIL SA	Pol Industrial Can Sedó, Carrer Cotó, Naves B-B4 08292 Esparraguera Barcelona (Spain)	Washing Range and Bianco Rope opener	Inspection and acceptance	BHANDARI HOSIERY EXPORTS LIMITED	RFI Number: COM-081425 / IRN : 2931104 OUR EMAIL REF: 11318368	2022	It has been done the physical inspection, the date of manufacturing, performance / running testing with satisfactory result
MECESA	C/ Joan Monpeó, 35 08223 Terrassa, Barcelona, SPAIN	Condensate POT 3"	Inspection and acceptance	SABIC UK Petrochemicals	Teesside improvement project	2022	Final inspection of the condensationate pot, PIM final stage
INTERNATIONAL CAPACITORS	Sta Perpetua de la Mogoda (Barcelona), Spain	Capacitors Banks 270 kVr and 390 kVr	Inspection and acceptance	ABENGOA	Red Sea Utility Assets and Infrastructure Project	2022	It has been done the wiring review, fixin fastening and interlocking, computer programming and relays, verification of the maneuver and discharge of the interlock, insulation distance check, voltage withstanding test and insulation resistance
MK4	Lliça de Vall (Barcelona, Spain)	Bearing Pots	Inspection and acceptance		4TH BRIDGE – IRAQ	2022	Final inspection on bearing pots, dimensional, paint control and material certificate review
IDEMAG	Pol. Ind. Llobregat, Bari,Nave 4 08755 Castellbisbal BARCELONA SPAIN	Magnetic Separator	Inspection and acceptance	Worley Services UK Limited	SPEAR Geleen Plant Balance of Plant EPCm Project	2022	It has been done the FAT test on the magnetic separator and the review of the documents as per supplied document requirements
VALVULAS NACIONAL	Compositor Vivaldi, 2-8 - P. Ind. "Can Jardi" - 08191 RUBI (Barcelona – Spain)	SAFETY-RELIEF VALVES	Inspection and acceptance	bs&b	Midland Refineries Co- Dau-ra- /Ministry of Oil-D/1426	2022	It has been done the set pressure test and the tightness test of the safety relief valves, additionally has been done the dimensional test and the review of the certificates

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
AGUILAR SALAS TORRES SL	Pol. Industrial Pla de Llerona c/Irlanda, 6 08520 - Les Franqueses del Vallès, Barcelona (Spain)	LC-MAX Reactor	Inspection and acceptance	TUV INDIA	HPCL VRMP RUF Unit	2022	It has been done the final inspection of the LC-MAX Reactors, it has been verify the painting and the assembly of the equipments
MK4	Lliça de Vall (Barcelona, Spain)	Bearing Pots	Inspection and acceptance		4TH BRIDGE – IRAQ	2022	Final inspection on bearing pots, dimensional, paint control and material certificate review
VALVULAS NACIONAL	Compositor Vivaldi, 2 - 8 Polígono Ind. "Can Jardí" P. O. Box 123 08191 - Rubí, BARCELONA (Spain)	Safety Relief Valves	Inspection and acceptance		Midland Refineries Co- Dau-ra- /Ministry of Oil-D/1426	2022	Leak test, hidrostatic test, visual inspection and general condition of the valves, according to the standard ASME v111, DIV.1 UG-136 (D)(2)
IBERFLUID INSTRUMENTS S.A	Carrer de la Botànica, 122, 08908 L'Hospitalet de Llobregat, Barcelona	SAMPLING SYSTEM	Inspection and acceptance	HELLENIC PETROLEUM		2022	During the inspection it has been review the certificate of the material, it has been carried out the visual and dimensional inspection and the verification of the nameplates of the equipments
IBERFLUID INSTRUMENTS S.A	Carrer de la Botànica, 122, 08908 L'Hospitalet de Llobregat, Barcelona	SAMPLING SYSTEM	Inspection and acceptance	HELLENIC PETROLEUM		2022	During the inspection it has been review the certificate of the material, it has been carried out the visual and dimensional inspection and the verification of the nameplates of the equipments
RIERA NADEU	C/ Cal Ros dels Ocells nº 1-3, Pol. Ind. Coll de la Manyà, 08403 Granollers, Barcelona	CENTRIFUGE / 01-390-3-CC-001 A/B	Inspection and acceptance	ENPPI	K411 - MEG REGENERATION AND RECOVERY UYNITS	2022	It has been done the final inspection of the equipment, it has been done the rotational speed test
PEKOS VALVES	Rec del Molinar 9, P.L El Circuit 08160 Montmeló - Barcelona	Ball Valves	Inspection and acceptance	RAIZEN ARGENTINA SA	RAIZEN ARGENTINA SA / PQ2024	2022	It has been done the ITP Step 8,3 Functional test on the safety valves
AGUILAR SALAS TORRES SL	Pol. Industrial Pla de Llerona c/Irlanda, 6 08520 - Les Franqueses del Vallès, Barcelona (Spain)	LC-MAX Reactor	Inspection and acceptance	TUV INDIA	HPCL VRMP RUF Unit	2022	It has been done the final inspection of the LC-MAX Reactors, it has been verify the painting and the assembly of the equipments
MK4	Lliça de Vall (Barcelona, Spain)	Bearing Pots	Inspection and acceptance	KUWAIT ARAB CONTRACTORS	RA-265 - Al Ghouse to 7th Ring Road – KUWAIT	2022	Final inspection on bearing pots, dimensional, paint control and material certificate review
Desarrollo Técnicas Industriales de Galicia S.A. (DETEGASA) Grupo Argos	Rúa Condesa Cavalcanti, 15540, A Coruña	Sewage Treatment Plant SSTPN-4050 and Grease Trap TG-600	Inspection and acceptance	YINSON	FPSO Maria Quitera	2022	It has been verify that all the components has the correct labeling, it has been done the functional test of the equipment and it has been check after the test
AGUILAR SALAS TORRES SL	Pol. Industrial Pla de Llerona c/Irlanda, 6 08520 - Les Franqueses del Vallès, Barcelona (Spain)	Mixed Acid Tank A/B including Agitator	Inspection and acceptance	KBR - PLINKE	Mixed Acid Tanks	2022	It has been done the final inspection of the Mixed Acid tanks, it has been verify the painting and the assembly of the equipments, the dryness and cleanliness, picklink and passivation and the revision of the name plates
Desarrollo Técnicas Industriales de Galicia S.A. (DETEGASA) Grupo Argos	Rúa Condesa Cavalcanti, 15540, A Coruña	Sewage Treatment Plant SSTPN-4050 and Grease Trap TG-600	Inspection and acceptance	YINSON	FPSO Maria Quitera	2022	It has been Close out of the punch list points for both units 66XF001A and 66XF001B

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
Desarrollo Técnicas Industriales de Galicia S.A. (DETEGASA) Grupo Argos	Rúa Condessa Cavalcanti, 15540, A Coruña	Oil water separator OWSAN-5	Inspection and acceptance	YINSON	FPSO Maria Quitera	2022	It has been done the final inspection for the oil separators, it has been verify the P&ID, the control drawing and the name plates of the equipment
TECNO-ELÈCTRIC GIRONA	<u>Calle del Río Güell, 34, 17180 Vilablareix, Girona</u>		Inspection and acceptance		150 MLD LAGUNA LAKE WATER TREATMENT PLANT	2022	XXX
ELTHERM	Carrer de Roser Dolçet, 1 08800 vilanova I la Geltrú	MATERIAL PARA CALENTAR CONDUCTO	Inspection and acceptance	WOOD	Augmento de capacidad red de AV A RGSR	2022	It has been done the checking of the all items
WIKA	08205 Sabadell	INSTRUMENTOS DE MEDIDA	Inspection and acceptance	ACCIONA	LAGUNA LAKE WATER TREATMENT PLANT	2022	It has been done the inspection of pressure gauges,flow switches, pressure switches, temperature switches and transmitters and by pass level indicators
FATOR	C/ Catalunya No.11 - P.I. Can Oller 08130 Santa Perpètua de Mogoda, Barcelona (SPAIN)	TORNILLERIA INDUSTRIAL	Inspection and acceptance	NSF	N/A	2022	It has been done the visual inspection of the selected material. The material is in good appearance and correct galvanized, also the material has the corresponding grade marking.
CONSERGRA	Carrer de pons i Enrich, 8, 08243 Manresa, Barcelona	Grain chiller	Inspection and acceptance	ALTUNTAS HAVALANDIRMA TURIZM TURIZM SAN. TIC.A.S ORGANIZE SAN.BOLGESI MEHMET	X	2022	The Inspection took place at the manufacturer Consergra workshop in Manresa for the preshipment ot the grain temperratura control unit (CONSERFRIO F550TD). Capacity 90 kW. First of all the inspector identified that the presented material comply with the comercial offer JRR OF.240521/B accepted by ALTUNTAS
PRESCAD	Camí de Can Ballús, 129B, Pol. Ind. La Valldan, 08600 Berga, Barcelona	STAINERS	Inspection and acceptance	SK IE Technology	Europe PH-3/4 PROJECT	2022	It has been done all the review of the stainers
PEDRO GIL	Polígono Industrial Vallmorena, Carrer Salvador Albert i Riera, 9, 08339 Vilassar de Dalt, Barcelona	blowers	Inspection and acceptance	ENGICO		2023	
SOLER&PALAU INDUSTRIES SLU	Crta. Puigcerda, s/n 17500 Ripoll (Girona) Spain	Exhaust fan	Inspection and acceptance	SAIPEM		2023	It has been verified all ITP points on exhaust fans
CONTRATOS Y DISEÑOS INDUSTRIALES	C/Guifre 799, 08918 Badalona (Barcelona)	SS PRESSURE VESSELS	Inspection and acceptance	KT	4305	2023	
INGEPERFIL	C/Argent,2 – Pol. Ind. Sant Francesc 08755 – Castellisbal (Barcelona).	STI-H250 Solar Tracker	Inspection and acceptance	ENEL	Dulcinea	2023	It has been done Visual (V), dimensional check (DC) and/or coating check (CC)
COLWAY	Camí Can Ubach, Nave 30. Polígono Industrial Les Fallulles Sant Vicenç dels Horts Barcelona 08620 España	SWITCH, Router and equipments of the gabinets	Inspection and acceptance	SIEMENS ENERGY	SE SANCELA	2023	It has been done the final inspection of the gabinets, it has been verify that the instalation has been done correct and the equipments comply with the test
EGARINOX L&T	P.I. PROFITEX Ctra. Montcada, 750 Nave-24 08223 TERRASSA	FASTENERS	Inspection and acceptance	EPC-L&T	AR-RAS	2023	It has been done the dimensional control ans the material certificates review
MEKANO 4 S.A	Lliça de Vall (Barcelona, Spain)	Bearing Pots	Inspection and acceptance	-	RA/265- Al Ghouse road From 7th Ring Road to Fahaheel-Ahmadi road (Road 212)	2023	Final inspection on bearing pots, dimensional, paint control and material certificate review
EGARINOX L&T	P.I. PROFITEX Ctra. Montcada, 750 Nave-24 08223 TERRASSA	FASTENERS	Inspection and acceptance	EPC-L&T	AR-RAS	2023	It has been done the dimensional control ans the material certificates review

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
IBERFLUID INSTRUMENTS S.A	Carrer de la Botanica, 122 08908 Hospitalet de Llobregat	Piston valve	Inspection and acceptance	Amec Foster Wheeler Iberia – WOOD	-	2023	Visual and dimensional inspection, it has been reviewed the certificates
TECNIUM CASALS CARDONA SA	Ferran Casablanques, 24 Manresa, Barcelona 08243, Spain	Sprayers	Inspection and acceptance	Enter Engg	Construction of Samarkand Chemical complex	2023	It has been check the dimesions and reviewed the documents
INGEPERFIL	C/Argent,2 – Pol. Ind. Sant Francesc 08755 – Castellisbal (Barcelona).	STI-H250 Solar Tracker	Inspection and acceptance	ENEL	Dulcinea	2023	It has been done Visual (V), dimensional check (DC) and/or coating check (CC)
COLWAY	Camí Can Ubach, Nave 30. Polígono Industrial Les Fallulles Sant Vicenç dels Horts Barcelona 08620 España	SWITCH, Router and equipments of the gabinets	Inspection and acceptance	COLWAY 08 SOLARWIND	SAN LUIS	2023	It has been done the final inspection of the gabinets, it has been verify that the instalation has been done correct and the equipments comply with the test
COLWAY	Camí Can Ubach, Nave 30. Polígono Industrial Les Fallulles Sant Vicenç dels Horts Barcelona 08620 España	SWITCH, Router and equipments of the gabinets	Inspection and acceptance	COLWAY 08 SOLARWIND	GONZALEZ ORTEGA	2023	It has been done the final inspection of the gabinets, it has been verify that the instalation has been done correct and the equipments comply with the test
MEKANO 4 S.A	Lliça de Vall (Barcelona, Spain)	Bearing Pots	Inspection and acceptance	-	RA/265- Al Ghouse road From 7th Ring Road to Fahaheel-Ahmadi road (Road 212)	2023	Final inspection on bearing pots, dimensional, paint control and material certificate review
MOSDORFER	C/ Emporda 7, Pol. Ind. Congost 08403 Granollers, Barcelona, Spain	Dropper Fittings- 7480 Sets	Inspection and acceptance	L&T	CP-305	2023	It has been done Visual (V), dimensional check (DC) , bolt tests
PRESCAD	Camí de Can Ballús, 129B, Pol. Ind. La Valldan, 08600 Berga, Barcelona	STAINERS	Inspection and acceptance	TECNICAS REUNIDAS	OSTROŁĘKA Project - 9HA.02 CCGT	2023	It has been done mechanical tests and final inspection of the strainers
UNITECNO	UNITECNO BERGA, Pol. La Valldan, Camí Can Ballús 53 08600 Berga (Barcelona)	STAINERS	Inspection and acceptance	TECNICAS REUNIDAS	CENTRAL CICLO COMBINADO MERIDA MX	2023	It has been done mechanical tests and final inspection of the strainers
REDFLUID	Carrer de Foc, 5, 08227 Terrassa, Barcelona	flexible pipe assemblies	Inspection and acceptance	LRQA	PRJ11100412592-1	2023	Witness of pressure and electrical tests on flexible pipe assemblies; Verify that the tests are performed according to test protocol; Visual examination of flexible pipe assemblies to check no presence of leak; Review of calibration certificates; Review and signature of test reports;
MK4	Lliça de Vall (Barcelona, Spain)	Bearing Pots	Inspection and acceptance	-	WW-PR-2180049	2023	Final inspection on bearing pots, dimensional, paint control and material certificate review
PRESCAD	Camí de Can Ballús, 129B, Pol. Ind. La Valldan, 08600 Berga, Barcelona	STAINERS	Inspection and acceptance	TECHINT	134874-SOLTEX CHILE S.A.	2023	Review of material documents and hydrostatic test
UNITECNO	UNITECNO BERGA, Pol. La Valldan, Camí Can Ballús 53 08600 Berga (Barcelona)	STAINERS	Inspection and acceptance	TECNICAS REUNIDAS	CENTRAL CICLO COMBINADO MERIDA MX	2023	It has been done mechanical tests and final inspection of the strainers
PEKOS VALVES S.L.U	Rec del Molinar, 9 E-08160 Montmeló (Barcelona)	Valves	Inspection and acceptance	WORLEY	BB001502	2023	Visual and dimensional test, open-close time check
TOSACA	Carrer de Guifré, 791, 08918 Badalona, Barcelona	Valves	Inspection and acceptance	Qmat Al Salsibil for Trading & project management	QS-PO-3110	2023	Functional, visual and dimensional check