

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	KEC International LTD.	380kV OHTL BETWEEN	2009	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	AL SHARIF KEC	CONSTRUCTION OF 110 KV OHTL FOR GULF SALMAN S/S	2015	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	Zakum Development Company (ZADCO)	UZ750 Project – EPC-2 (ZADCO PROJECT NO. P7512)	2015	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	LARSEN & TOUBRO SAUDIARABIA LLC	SOUTHERN AREA OIL OPERATION(SAOO) POWER SYSTEM RELIABILITY IMPROVEMENT PROJECT-115KV	2016	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	WORLEY PARSONS	QCLNG UPSTREAM PROJECT	2016	
OPTRAL SA	Poligono Industrial, Ctra. BV-5128 KM-22, 08359 St. Iscle de Vallalta, Barcelona	Optical fiber cable	Inspection and acceptance	PROMAEL	NUEVOS COMPRESORES EN FCC PARA MEJORA DE EFICIENCIA ENERGETICA	2016	
OPTRAL SA	Poligono Industrial, Ctra. BV-5128 KM-22, 08359 St. Iscle de Vallalta, Barcelona	Optical fiber cable	Inspection and acceptance	ACWA POWER	NOORO II CSP POWER PLANT	2016	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	ADCO ABU DHABI	EPC FOR AL DABB'YA FACILITIES DEVELOPMENT PHASE III	2016	
OPTRAL SA	Poligono Industrial, Ctra. BV-5128 KM-22, 08359 St. Iscle de Vallalta, Barcelona	Optical fiber cable	Inspection and acceptance	IAC	FELGUERA IHI PROYECTO 785-768	2016	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	VBMS	HORNS REV 3	2017	
OPTRAL SA	Poligono Industrial, Ctra. BV-5128 KM-22, 08359 St. Iscle de Vallalta, Barcelona	Optical fiber cable	Inspection and acceptance	TECNIMONT S.P.A	3872 NH3 KINGISEPP (RU) EPC	2017	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	R&M ELECTRICAL	BP - SNG UHF SYSTEM UPGRADE, Azerbaijan	2017	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	QATAR ENGINEERING & CONSTRUCTION CO.	TREATED INDUSTRIAL & PROCESS WATER	2017	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	QATAR GENERAL ELECTRICITY & WATER CORPORATION	QATAR POWER TRANSMISSION SYSTEM EXPANSION - PHASE 11	2017	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	COMISION FEDERAL DE ELECTRICIDAD	REPOSICION ALMACEN	2018	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	COMISION FEDERAL DE ELECTRICIDAD	PARQUE EOLIICO REYNOSA	2018	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CHIYODA CCC	EPC FOR ZIRKU FACILITES CAPACITY ENHANCEMENT PROJECT	2019	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	VBMS	HORNS REV 3	2019	
OPTRAL SA	POLIGONO INDUSTRIAL CTRA. BV-5128 KM 22 - 08359 – SANT ISCLE DE VALLALTA (BARCELONA) ESPAÑA	Optical fiber cable	Inspection and acceptance	ENI SPA	ALGERIA PIPELINE BRN MLE	2019	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	ALDHAFRA PETROLEUM	HALIBA FIELD DEVELOPMENT PROJECT	2019	
OPTRAL SA	Carretera BV-5128 Km. 22 08359 - Sant Iscle de Vallalta (BARCELONA)	Optical fiber cable	Inspection and acceptance	GRS-ACCIONA-GHELLA	DEWA PHASE III-B 800MW SOLAR POWER PLANT	2019	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE(Confederacion Federal de Electricidad)	REPOSICION ALMACEN PRYSMIAN Cables y Sistemas de México, S de RL de CV	2019	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE(Confederacion Federal de Electricidad)	PPAF 6886	2019	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE(Confederacion Federal de Electricidad)	PPAF 6886	2019	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	SHANDZ COMPANY FOR ELECTRICAL AND CONSTRUCTION CONTRACTS	33 kV OHTL Cedros Factory	2019	

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Purpose
OPTRAL SA	Poligono Industrial, Ctra. BV-5128 KM-22, 08359 St. Iscle de Vallalta, Barcelona	Optical fiber cable	Inspection and acceptance	ENI SPA	INGENIERIE DE BASE PIPELINE GAZ BRN-MLE - Sonatrach - R 0817-WO5	2019	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	AD NOC	EPC FOR AL DABB'IYA THAMMAMA ZONE B TRANSITION ZONE DEVELOPMENTS - PHASE 1 (15 WELLS) & RESTORE AL DABB'IYA OTHER ZONE (OZ) PRODUCTION (17 WELLS)	2019	
OPTRAL SA	Carreretar BV-5128 km 22 08359 - Sant Iscle de Vallalta	Optical fiber cable	Inspection and acceptance	SACYR INDUSTRIAL	ALENA WIND FARM	2020	Visual inspection and NDT
OPTRAL SA	Carreretar BV-5128 km 22 08359 - Sant Iscle de Vallalta	Optical fiber cable	Inspection and acceptance	FINIS TERRAE EXT	FINIS TERRAE EXT	2020	Construction of the cable, fiber identification, dimensional, attenuation and review of the documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2020	Visual inspection and review of the routine test done by the factory
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CONCO		2020	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION	PROYECTO DE CONECTIVIDAD FIBRA OPICA RED ELECTRICA INTELIGENTE REI	2020	Visual inspection and review of the routine test done by the factory
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2020	Visual inspection and review of the routine test done by the factory, tensile strenght and elasticity module of the cable
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	INABENSA	Replacament of the Faulty OPGW with new OPGW between shahama east 400 kV G/S	2020	FAT Test on 15 Drums of OPGW and 17 Units of joint boxes
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2020	Atenuation test and visual inspection of the PO
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGOIONAL DE TRANSMISIÓN NOROESTE	PRYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	Routine test and acceptance test, inspection of the documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN CENTRAL	PRYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	Visual inspection of complete PO, Routine test of the selected drums
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN NORTE	PRYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	Visual inspection of complete PO, Routine test of the selected drums
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN OCCIDENTE	PRYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	Visual inspection of complete PO, Routine test of the selected drums
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	KAHROMIKA	Triple Bundle 220kV double circuit OHTL (Lot 1, 2, 3) October/ Al Ashier Project in EGYPT	2021	Review of packing list, and ITP test according to IEC 61232 and IEC 60104, visual inspection and review of the documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	Abu Dhabi Transmission and despatch company	Etihad Rail Package 2D (Notherm Emirates) - OHL	2021	Visual inspection of complete PO, Routine test of the Joint Boxes
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	ARABIAN ELECTRICAL TRANSMISSION	CONSTRUCTION OF ONE 380 KV OHTL BETWEEN FADHILI GAS PLANT S/S TO WADI AL-SUMMAN 380/115/33KV BSP	2021	Review of packing list, and ITP test according to IEC 61232 and IEC 60104, visual inspection and review of the documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN CENTRAL	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN CENTRAL	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN NORTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	FAT test on finished cable according to the standard, IEC61089, EN50182, IEC 61232
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN NORTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	FAT test on finished cable according to the standard, IEC61089, EN50182, IEC 61232

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Purpose
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN OCCIDENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN CENTRAL	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISION SURESTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN CENTRAL	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN VALLE DE MEXICO	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN ORIENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	Federal electricity and water authority (FEWA)	Etihad Rail Package 2D (Northem Emirates) - OHL Modification and diversion works in fujairah	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN ORIENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN ORIENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	NESTE OIL	NESTE PROJECT	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN SURESTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISIÓN GERENCIA REGIONAL DE TRANSMISIÓN OCCIDENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	NESTE OIL	220kV OHTL (Lot1) Badr 500 / LRT1 & (Lot2) El Ashier 500/LRT 2 Project in Egypt	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN SURESTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	Technip	SINGAPORE EXPANSION PROJECT	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN OCCIDENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	GERENCIA REGIONAL DE TRANSMISIÓN PENINSULAR	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	GERENCIA REGIONAL DE TRANSMISIÓN BAJA CALIFORNIA	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION GERENCIA REGIONAL DE TRANSMISIÓN OCCIDENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	View of the cable, FAT test and optical atenuation according to the standard IEC 60793 - 1- 40
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	NESTE OIL	220kV OHTL (Lot1) Badr 500 / LRT1 & (Lot2) El Ashier 500/LRT 2 Project in Egypt	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	Abu Dhabi Transmission and despatch company	ETIHAD RAIL PACKAGE 2D (NORTHERN EMIRATES) OHL	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	Abu Dhabi Transmission and despatch company	ETIHAD RAIL STAGE 2 PROJECTS C0304-PACKAGE 2B Design and Build contract (Tarif-Seih Shauib)	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION Gerencia Regional de transmisión peninsular	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	The scope of inspection was witness of routine test on one drum per cable type.

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Porpose
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION Gerencia Regional de transmisión noroeste	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION Gerencia Regional de transmisión Baja california	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION Gerencia Regional de transmisión ORIENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION Gerencia Regional de transmisión OCCIDENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION Gerencia Regional de transmisión CENTRAL	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	CFE TRANSMISION Gerencia Regional de transmisión ORIENTE	PROYECTO DE CONECTIVIDAD FIBRA OPTICA RED ELECTRICA INTELIGENTE REI	2021	The scope of inspection was witness of routine test on one drum per cable type.
OPTRAL SA	Crta BV-5128 Km-22 08359 Sant Iscle de Vallalta Barcelona	Optical fiber cable	Inspection and acceptance	GLOBAL ENERGY SERVICES GES	TICO I&II	2021	It has been done the attenuation test of the fiber optic cable according to the standard IEC 60793-1-40, the dimensional inspection of the cables and marking verification, also it has been done the review of the documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	SAIPEM	Arctic LNG 2 LLC	2021-2022	The scope of inspection was witness of routine test on one drum per cable type.
OPTRAL SA	Crta BV-5128 Km-22 08359 Sant Iscle de Vallalta Barcelona	Optical fiber cable	Inspection and acceptance	GLOBAL ENERGY SERVICES GES	TICO II	2021	It has been done the attenuation test of the fiber optic cable according to the standard IEC 60793-1-40, the dimensional inspection of the cables and marking verification, also it has been done the review of the documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance		EETC - Egyptian Electricity Transmission Company Project No (32-2018/2019)	2021	It has been done the attenuation test of the fiber optic cable according to the standard IEC 60793-1-40, the dimensional inspection of the cables and marking verification, also it has been done the review of the documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	KAHROMIKA	220kV OHTL (71/2019/202) Project in Egyp	2021	The scope of inspection was witness of routine test on one drum per cable type.
OPTRAL SA	Crta BV-5128 Km-22 08359 Sant Iscle de Vallalta Barcelona	Optical fiber cable	Inspection and acceptance	ABENGOA	Red Sea Utility Assets and infrastructure Project	2021	It has been done the attenuation test of the fiber optic cable according to the standard IEC 60793-1-40, the dimensional inspection of the cables and marking verification, also it has been done the review of the documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	KAHROMIKA	220kV OHTL (Lot1) Badr 500 / LRT1 & (Lot2) El Ashier 500/LRT 2 Project in Egyp	2021	The scope of inspection was witness of routine test on one drum per cable type.
TOP CABLE	C/Leonardo Da Vinci. 1, 08191 Rubí (Barcelona)	Optical fiber cable	Inspection and acceptance	ENEL GREEN POWER	CAMPOS DEL SOL 2 BOP - CL	2021	It has been done the visual aspect, optical attenuation, optical continuity, rutine test according to the standard IEC 607932-2 and IEC 60794-3 for the 10% of the drums
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	PRYSMIAN	Ethad rail packaged 2d (Northern Emirates) - OHL modification and diversion works in Fujairah 78977-5	2022	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	SONABEL	PROJET D'APPUI AU SECTEUR DE L'ELECTRICITE (PASEL) FINANCEMENT BANQUE MONDIALE	2022	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	General Cable mexico	INGENIERIA EN INSTALACIONES CDC SA DE CV	2022	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	SAMSUNG	INDEPENDENT SUBSEA HVDC SYSTEM PROJECT (Project Lightning) IN U.A.E.	2022	The scope of inspection was witness of routine test on one drum per cable type.
OPTRAL SA	Polig. Ind. Carretera BV-5128, KM22 08359 – Sant Iscle de Vallalta (Barcelona) - Spain	Optical fiber cable	Inspection and acceptance	ABENGOA	Red Sea Utility Assets and Infrastructure Project	2022	It has been done the FAT test on the fiber optical cable, it has been done the attenuation of the cable, the cable printing marks, fiber optics icentification/color and the review of the material

Supplier's Name	Location	Equipment Description	Service Provided	Client	Project	Year	Inspection Purpose
PRYSMIAN ADNOC	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	Samsung C&T Corp.	INDEPENDENT SUBSEA HVDC SYSTEM PROJECT (Project Lightning) IN U.A.E.	2022	It has been done the FAT test on the optical cable, it has been done the attenuation, the verification of the fibers and the review of the materials
OPTRAL	Carretera BV-5128 KM 22. 08359 Sant Iscle de Vallalta, Barcelona, España	Optical fiber cable	Inspection and acceptance	ENEL	EL MANZANO SOLAR	2022	It has been done the packing inspection of the drums, it has been verify that the drums are ready for the delivery, it has verify the packaging protection of the drum.
OPTRAL	Carretera BV-5128 KM 22. 08359 Sant Iscle de Vallalta, Barcelona, España	Optical fiber cable	Inspection and acceptance	OHL	PROYECTO CEDILLO III	2022	It has been done the packing inspection of the drums, it has been verify that the drums are ready for the delivery, it has verify the packaging protection of the drum.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	RTE	YEU-NOIRMOUTIER OFFSHORE WINDFARM	2023	It has been done the FAT test on the optical cable, it has been done the attenuation, the verification of the fibers and the review of the materials
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	SAMUSUNG	INDEPENDENT SUBSEA HVDC SYSTEM PROJECT	2023	It has been done the FAT test on the optical cable, it has been done the attenuation, the verification of the fibers and the review of the materials
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	ENI	DGS Electrical Integration-PHASE 2 (Zubair Mishrif & Rafidiya), IRAQ	2023	It has been done the FAT test on the optical cable, it has been done the attenuation, the verification of the fibers and the review of the materials
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	SAMUSUNG	INDEPENDENT SUBSEA HVDC SYSTEM PROJECT	2023	It has been done the FAT test on the optical cable, it has been done the attenuation
Lannion iXblue SA	Rue Paul Sabatier 22300, Lannion, France	Optical fiber cable	Inspection and acceptance	-	-	2023	
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	SAMUSUNG	INDEPENDENT SUBSEA HVDC SYSTEM PROJECT	2023	It has been done the FAT test on the optical cable, it has been done the attenuation
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	NATIONAL CONTRACTING COMPANY LTD.	ABU DHABI TRANSMISSION & DESPATCH COMPANY TRANSCO Contract N-16834	2023	It has been reviewed the fat documents
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	TAS Energy for Electromechanical Works LLC	400kV Single Circuit Overhead Transmission Line Qaim –Risha IN IRAQ	2023	The scope of inspection was witness of routine test on one drum per cable type.
PRYSMIAN	C-15, Km 2, Vilanova i La Geltru, 08800 (Barcelona)	Optical fiber cable	Inspection and acceptance	Samsung	INDEPENDENT SUBSEA HVDC SYSTEM PROJECT	2023	FAT tests